



U.S. Department of Transportation

National Highway Traffic Safety Administration

Dear Crash Data Researchers/Users:

Thank you for choosing crash data from the National Highway Traffic Safety Administration (NHTSA) for your research or other use. The information contained in this motor vehicle crash report is collected, maintained and distributed in accordance with Public Law 89-564. In accordance with this Public Law, NHTSA is required not to release any case information until completion of quality control procedures. These procedures include a review of the case material to extract all names, licenses and registration numbers, non-coded interview material, non-research related researcher comments in the margins, non-factual data, and the production number portion of the vehicle identification number (VIN).

If you requested NHTSA to query its database files in order to identify a specific crash, then that query was made using non-personal descriptors you provided for use in our search. This motor vehicle crash may have been identified from a data search and matches the general, non-personal descriptors you provided, but we cannot confirm that this is the specific crash report you requested.

If you have any questions with regard to the above procedures, please contact the Field Operations Branch, Crash Investigation Division, National Center for Statistics and Analysis at 202-366-4820. Again, please be advised that we cannot confirm that this is the case that you have specifically requested nor can we certify the information to be correct.

*** *** ***



Case Vehicle (A): 2000 Dodge

Type: Dakota, 4X2 pickup

Vehicle (B): Military truck

Type: 5-ton cargo truck w/ trailer

Driver: 63-year-old female Driver: 36-year-old male

CDC: 12-FDEW-4 CDC: 99-0000-0

SITUATION

(Slide 1) Case vehicle (A) was traveling in the outside eastbound lane of a straight section of a dry concrete, eight-lane divided highway, (slide 2) with a posted speed limit of 105 kph (65 mph). Vehicle (B) was traveling in the same eastbound lane, towing a trailer, and was stopped in traffic with its emergency lights flashing. The driver of case vehicle (A) did not realize that vehicle (B) was stopped until a collision was impending. The driver of case vehicle (A) reportedly attempted to avoid a collision by braking, but the front end of case vehicle (A) struck the trailer being towed by vehicle (B). Case vehicle (A) underrode the trailer, resulting in an inverted step pattern of direct damage to case vehicle (A).

GENERAL VEHICLE DAMAGE AND ESTIMATED CRASH SEVERITIES

(Slides 3, 4, 5, 6, 7, 8) Damage to case vehicle (A) was severe. The direct-damage length was 145 cm and involved the entire front end. The maximum crush at the bumper level was 38 cm and occurred at the right-front bumper corner. The maximum crush at the hood level was 94 cm. The bumper was rotated upward. The right wheelbase was reduced 11 cm, and the left wheelbase was extended 7 cm.

Using the WinSMASH accident-reconstruction program and averaged c-values for the bumper-level and hood-level crush for case vehicle (A), the following impact severity was calculated:

		Calculated	Velocity Change	- kph (mph)
Vehicle	Variable	Total	Longitudinal	Latitudinal
Case Vehicle (A)	EBS	57 (35)	-57 (-35)	0 (0)

DESCRIPTION OF DAMAGE TO CASE VEHICLE (A)

Exterior

(Slides 9, 10, 11, 12, 13) The front bumper, both headlight assemblies, the radiator, the grille, the hood, and both fenders were damaged by direct contact. The right roof siderail was slightly buckled. The hood was crushed, (slide 14) the hood latch was damaged and released, and both hood hinges were damaged, but did not separate. The windshield was damaged as the hood was crushed rearward. (Slides 15, 16) The rear edge of the hood was elevated and contacted the windshield, resulting in an 18-cm hole in the lower right corner of the windshield. (Slides 17, 18) The cab contacted the cargo box. Both front doors were displaced slightly rearward and the hinges were sprung. Both of the right-side windows were shattered.

Interior

(Slides 19, 20, 21, 22) This vehicle was equipped with both steering-wheel and passenger frontal-impact airbags, which deployed during the frontal impact. (Slides 23, 24, 24, 25, 26, 27, 28) No damage was noted to the airbag module doors/flaps. (Slide 29, 30, 31) The steering-wheel rim was not deformed, but the steering wheel was cut from the vehicle during extrication of the driver. (Slides 32, 33, 34, 35, 36, 37, 38) The windshield was cracked and holed from contact by the hood, and there was blood and skin on the right side of the broken windshield glass. The right side of the windshield was contacted by the right-front passenger, and both right-side windows were shattered. There were several blood stains on the top, top front, and right sides of the passenger frontal-impact airbag. (Slide 39) The rearview mirror was broken off of its mount. There were scuff marks on the transmission selector lever from occupant contact. The hand hold on the A-pillar, the mid and lower instrument panels, and the glovebox were damaged and scuffed by occupant contact. The instruments, climate control vents, and parking brake release were damaged. (Slides 40, 41, 42) The following intrusions were noted and measured:

Location	Component	Distance (cm)	Direction
left front	instrument panel	19	to rear
center front	instrument panel	23	to rear
right front	instrument panel	8	to rear

OCCUPANT INJURIES AND KINEMATICS

The 5-ft, 6-in, 200-lb, 63-year-old female driver (slides 43, 44) was <u>not</u> wearing the available three-point belt, and the steering-wheel airbag deployed. (Slides 45, 46, 47) On impact, she moved forward into the airbag, but (slides 48, 49) it does not appear that she contacted the windshield header. She sustained police-reported "A", or incapacitating, injuries, but injury details from hospital records are not available.

The 6-ft, 0-in 176-lb 74-year-old male, right-front passenger (slides 50, 51) was *not* wearing the available three-point belt and the passenger frontal-impact airbag deployed. On impact, (slide 52, 53) he moved forward into and over the airbag, and into the windshield, but it (slide 54) does not appear that he contacted the windshield header or sunvisor. He sustained a laceration that partially split the nose, and a displaced fractured, nose (slide 55) from contact with the windshield, as evidenced by skin and hair deposits. He also sustained a contusion to the right eye, and a comminuted fracture to the right superomedial maxillary sinus/orbital floor with a displaced fracture of the superior lateral maxillary wall, probably from facial contact with the windshield while it was loaded by the crushed hood. He sustained a comminuted fracture to the distal right radius, (slide 56) probably from the airbag flinging his arm into the right upper-A-pillar-mounted hand hold, as evidenced by a scuff mark and hair deposits. He also sustained comminuted fractures of the right tibial plateau and the left patella, (slides 57, 58) from foot and knee contact with the knee bolster and glove box area, respectively as evidenced by a scuff mark on the knee bolster.

The following tables and attached drawings (slides 59, 60) summarize the injuries sustained by the driver and right-front passenger.

Occupant: Driver
Restraints: 3-point belt <u>not</u> worn; airbag deployed

Age: 63 years Stature: 168 cm (5 ft, 6 in)

Gender: Female

Mass: 91 kg (200 lb)

			Injury Source	
Injury Description	A.I.S.	Definite	Probable	Possible
Police reported "A" (incapacitating) injuries	7			Unknown
Maximum A.I.S. Level	7			
Injury Severity Score	<u>99</u>			

Occupant: Right front
Restraints: 3-point belt <u>not</u> worn; airbag deployed

Age: 74 years Stature: 183 cm (6 ft, 0 in)

Gender: Male

Mass: 80 kg (176 lb)

			Injury Source			
Injury Description	A.I.S.	Definite	Probable	Possible		
Laceration, partially spliting the nose	1	Windshield (loaded by hood)				
Fracture, displaced nose	2	Windshield (loaded by hood)				
Contusion, right eye	1		Windshield (loaded by hood)			
Fracture, comminuted to the right superomedial maxillary sinus/orbital floor with a displaced fracture of the superior lateral maxillary wall	3		Windshield (loaded by hood)			
Fracture, comminuted, distal right radius	3		A-pillar mounted hand hold (airbag fling)			
Fracture, comminuted, right tibial plateau	3		Knee bolster/glove box area			
Fracture, comminuted, left patella	2		Knee bolster/glove box area			
Maximum A.I.S. Level	<u>3</u>					
Injury Severity Score	<u>19</u>					

Duplicate columns 1-8 Module G Format (from the previous card.) <u>2</u> 1 12	GENERAL INFORMATION	GI-1
	1 12 y y	GENERAL INFORMATION ENVIRONMENTAL CONDITIONS CONSTRUCTION ZONE (0) NO (1) YES (9) UNKNOWN ROAD ALIGNMENT VERTICAL PLANE (1) LEVEL (2) CREST OF HILL (3) SLOPE (2%) (4) BOTTOM OF HILL (9) UNKNOWN ROAD ALIGNMENT HORIZONTAL PLANE (1) STRAIGHT (2) CURVE (3) T - SHAPED (4) Y - SHAPED (4) Y - SHAPED (7) OTHER: (9) UNKNOWN SURFACE COVERING (10) DRY (21) WATER - DAMP (22) WATER - WET (23) WATER - PUDDLED (29) WATER - AMOUNT UNKNOWN (31) SNOW - LOOSE (32) SNOW - PACKED (39) SNOW - CONDITION UNKNOWN (41) ICE (51) SLUSH (61) SPILLED GRAVEL	GI-1
(6) PARKING LOT/DRIVEWAY (7) OTHER: (9) UNKNOWN INTERSECTING RD, TOTAL LANES CHOOSE FROM ABOVE LIST, OR (8) NOT APPLICABLE TYPE OF ROAD SURFACE (1) ASPHALT (2) CONCRETE (3) GRAVEL (4) MORE THAN ONE (CIRCLE EACH) (7) OTHER: (9) UNKNOWN ROAD DEFECTS (0) NO (1) YES (9) UNKNOWN	$\frac{8}{30}$ $\frac{3}{31}$	(71) OTHER: (99) UNKNOWN VISIBILITY LIMITATION (FOR CASE VEHICLE) (0) NONE (1) CLOUDY/DARK (2) FOG (3) SMOKE (4) WINDSHIELD CONDITION (5) GLARE (6) RAIN (7) OTHER: (8) ICE/SNOW (9) UNKNOWN VISIBILITY OBSTRUCTION (FOR CASE VEHICLE) (0) NONE (1) BUILDING (2) SIGN (3) VEGETATION (E.G. BUSHES, SHRUBS) (4) TREE (5) HILL OR CURVE IN ROAD (6) VEHICLE IN TRANSPORT (7) OTHER: (8) PARKED VEHICLE	<u>Ø</u> 39

		GENERAL INFORMATION G	1-2
ENVIRONMENTAL CONDITIONS SPEED LIMIT (0) 5-45 km/h 5-25 mph (1) 46-55 30 (2) 56-60 35 (3) 61-70 40 (4) 71-79 45 (5) 80-85 50 (6) 86-90 55 (7) 91-105 60 (8) OVER 105 65 (9) UNKNOWN	8 40	MECHANICAL MALFUNCTION WAS THERE MENTION OF A MECHANICAL MALFUNCTION IN CASE VEHICLE (0) NO (1) YES (2) YES, DID NOT CONTRIBUTE TO ACCIDENT (9) UNKNOWN	<u></u> 46
(0) NONE (1) RAIN (2) SNOW (3) HAIL (4) FREEZING RAIN/SLEET (7) OTHER: (9) UNKNOWN RATE OF PRECIPITATION (1) LIGHT/MIST (2) MODERATE (3) HEAVY (8) NOT APPLICABLE (9) UNKNOWN TEMPERATURE (0) BELOW -15° C BELOW 5° F (1) -15 TO -6	8 42 9 43	THE FOLLOWING SECTION SHOULD BE FILLED OUT IF A MECHANICAL MALFUNCTION IS RECOGNIZED OR SUSPECTED. CIRCLE ITEMS INVOLVED. SUPPORT ANY ITEMS CIRCLED WITH COMMENTS. BRAKE SYSTEM DRIVER CONTR EXHAUST SYSTEM POWER TRAIN STEERING SYSTEM FUEL SYSTEM SUSPENSION SYSTEM VISIBILITY ITEM ELECTRICAL SYSTEM TIRES THROTTLE CONTROLS UNKNOWN OTHER: COMMENTS:	S
CROSSWIND (0) NONE (1) LIGHT (2) STRONG (3) GUSTY & STRONG (9) UNKNOWN LIGHT CONDITIONS (1) DAYLIGHT (2) DAWN (3) DUSK (4) DARK, LIGHTED (5) DARK, UNLIGHTED (6) DARK, UNKNOWN IF LIGHTED (9) UNKNOWN	44		

		GENERAL INFORMATION	GI-3
CRASH DETAILS CASE VEHICLE AND OBJECT (0) NO (1) YES (9) UNKNOWN	<u></u>	HIGHEST POLICE INJURY SEVERITY CODE IN CRASH (NOT JUST CASE VEHICLE) (0) O - NO INJURY (1) C - POSSIBLE INJURY (2) B - NON-INCAPACITATING INJURY (3) A - INCAPACITATING INJURY (4) K - FATAL (5) INJURED, SEVERITY UNKNOWN	
CASE VEHICLE ROLLOVER (0) NO ROLLOVER (1) YES, FIRST EVENT (2) YES, SUBSEQUENT EVENT (3) YES, SEQUENCE UNKNOWN (9) UNKNOWN	45	(6) DIED PRIOR TO ACCIDENT (7) NON-FATAL INJURY SEVERITY UNKNOWN (9) UNKNOWN DRIVER IMPAIRMENT	3 55
CASE VEHICLE RAN OFF ROADWAY (BEFORE FIRST IMPACT) (0) NO (1) YES (9) UNKNOWN	<u>—</u>	DRIVER ALCOHOL INVOLVEMENT (CASE VEHICLE) (0) NONE (1) YES (9) UNKNOWN/NOT REPORTED/ NO DRIVER	<u>Ø</u>
MOVING CASE VEHICLE AND CONTACTED MOVING VEHICLE (0) NO (1) YES (9) UNKNOWN	<u>so</u>	DRIVER ALCOHOL BAC (CASE VEHICLE) (80) NO TEST (90) CHEMICAL TESTS, NO RESULTS (95) AUTOPSY, NO RESULTS (99) UNKNOWN	8 0 58
CASE VEHICLE AND CONTACTED STOPPED VEHICLE (0) NO (1) YES (9) UNKNOWN	51	WAS THERE MENTION OF DRIVER IMPAIRMENT FOR CASE VEHICLE? (0) NO (1) YES (9) UNKNOWN	Φ
STOPPED CASE VEHICLE AND CONTACTED VEHICLE (0) NO (1) YES (9) UNKNOWN TOTAL NUMBER	<u>D</u>	LIST IMPAIRMENTS MENTION	IED:
OF VEHICLES CONTACTED BY CASE VEHICLE IN CRASH (8) 8 OR MORE (9) UNKNOWN	53	POST - CRASH DETAIL MANNER CASE VEHICLE LEFT SCENE	
ANY FIRE IN THIS CRASH (NOT JUST CASE VEHICLE) (0) NO (1) YES (9) UNKNOWN	<u>Ø</u>	 (1) DRIVEN (2) TOWED DUE TO DAMAGE (3) TOWED, NOT DUE TO DAMAGE (4) TOWED, REASON UNKNOWN (9) UNKNOWN 	2 80

ACCIDENT DESCRIPTION: Case vehicle (A) was traveling in the outside	CASE VEHICLE (A): 2000 Podge Dkota	_
eastbound lane of a straight section of a dry, 8-lane divided highway. Vehicle	OTHER VEHICLE (B): Military truck w/trailer	_
(B) was traveling in the same eastbound lane, buing a trailer, and was	THIRD VEHICLE (C): N/A	_
Stopped in traffic with its emergency lights flashing. The driver of case		
(B) was stopped until a collision was imponding. The driver of case vehic		١
culliston by braking, but the front end of case vehicle (A) struck the trailer		,
vehicle (A) underrude the trailer, resulting in an inverted step pattern		l

Speed limit 65 mph							
A1 ►			→	A2 >	_ B1		

Duplicate columns 1-8 from the previous card. Module O V Format 0 4 11 12	OTHER VEHICLE OV-1
MAKE: Unknown MODEL: 5 ton military 5-ton Car	cargo: Unknown - towing trailer
VIN	
MANUFAC/BODY CODE MAKE/MODEL CODE MODEL YEAR $ \begin{array}{cccccccccccccccccccccccccccccccccc$	VEHICLE TYPE PASSENGER VEHICLE (02) LARGE (03) LIMOUSINE (17) PICKUP CAR (20) UNKNOWN PASSENGER VEHICLE BODY (24) SUB-MINI (25) MINI (26) SUB-COMPACT (27) COMPACT (28) INTERMEDIATE (29) FULL MULTIPURPOSE PASSENGER VEHICLE (14) SMALL UTILITY (WHEELBASE LESS THAN 107*, E.G. JEEP, BRONCO) (15) LARGE UTILITY (WHEELBASE MORE THAN 107*, E.G. PANEL TRUCK, SUBURBAN) (16) PICKUP TRUCK WITH CANOPY/SHELL COVER (17) PICKUP CAR WITH CANOPY/SHELL COVER (21) MOTOR HOME (22) PICKUP TRUCK WITH SLIDE-IN CAMPER (23) PICKUP CAR WITH SLIDE-IN CAMPER (31) CHASSIS-MOUNTED CAMPER
(000) PARKED OR STOPPED (995) JUST STARTING UP (996) BACKING UP (997) SPEED NOT EXCESSIVE (BUT UNKNOWN) (998) SPEED EXCESSIVE (BUT UNKNOWN) (999) UNKNOWN HIGHEST POLICE INJURY SEVERITY CODE FOR THIS VEHICLE (0) O - NO INJURY (1) C - POSSIBLE INJURY (2) B - NON-INCAPACITATING INJURY (3) A - INCAPACITATING INJURY (4) K - FATAL (5) INJURED, SEVERITY UNKNOWN (6) DIED PRIOR TO ACCIDENT (7) NON-FATAL INJURY SEVERITY UNKNOWN (8) UNOCCUPIED VEHICLE (NOT APPLICABLE) (9) UNKNOWN	TRUCK (11) VAN (12) PICKUP TRUCK (13) UNKNOWN LIGHT TRUCK (15) LARGE UTILITY (E.G. PANEL TRUCK, SUBURBAN) (16) PICKUP TRUCK WITH CANOPY/SHELL COVER (22) PICKUP TRUCK WITH SLIDE-IN CAMPER (30) UNKNOWN TRUCK TYPE (31) CHASSIS-MOUNTED CAMPER (33) DELIVERY VAN (WALK-IN) (34) STRAIGHT TRUCK (35) TRUCK-TRACTOR (BOBTAIL) (36) CHASSIS-CAB (37) UNKNOWN HEAVY TRUCK (38) TRACTOR & SEMI-TRAILER (SEMI) (39) TRUCK (OR SEMI) & FULL TRAILER(S) BUS (40) UNKNOWN BUS TYPE (41) SCHOOL BUS (42) INTERCITY BUS (BETWEEN CITIES) (43) TRANSIT BUS (INTRACTY) (44) STREETCAR (ON TRACKS) (68) TRAIN (CARS) (69) LOCOMOTIVE (ENGINE, SWITCHER)
	(99) UNKNOWN WHEELBASE (cm) (999) UNKNOWN

Duplicate columns 1-8 from the previous card.

Module <u>O</u> <u>V</u> Format <u>0</u> <u>2</u> 9 10 11 12 OTHER VEHICLE

OV-2

ORIGINAL SPECIFICATIONS

Wheelbase 9999 cm

Curb Weight 9999 k

Average Track Width 9999 cm

Overall Length 9999 cm

Overall Width (OAW) 9999 cm

Front Overhang

Rear Overhang

22 9 9 cm

Undeformed End Width (UEW)

9 9 9 cm

Engine Displacement

 $\frac{9}{31} \cdot \frac{9}{32}$

Engine: # of Cylinders

 $\frac{9}{33} \frac{9}{34}$

VEHICLE DAMAGE

Not inspected - No VIN reported

FRONTAL CRASH OVERLAP

Round up for .5. 98 = 98% or more Enter % overlap or "99" for missing or N/A. Direct Damage Length (DDL)

9 9 9 cm

Front-End Overlap (Percent) = DDL UEW

....

99%

Vehicle Overlap (Percent) = DDL + 1/2 (OAW - UEW)
OAW

99 %

Duplicate columns 1-8 Module V D Format 0 from the previous card. 9 10 11			VEHICLE DESCRIPTION	VD-1
MAKE: Dodge MODEL: Dakota club cab 4	γŁ		CARGO: None	
VIN 13 B 7 6 L 2	2 1	18	YS	29
MANUFAC/BODY CODE $\frac{1}{30}$ $\frac{32}{2}$	3	STOLE	N VEHICLE	
MAKE/MODEL CODE 332	<u> 5</u>			8 62
MODEL YEAR $\frac{2}{39} \frac{\cancel{0}}{\cancel{0}} \frac{\cancel{0}}{\cancel{0}}$		(3)	NAMOVAN	
VEHICLE MASS (kg) $igoplus_{43} {\cal D} \perp {igotimes} {\cal D}$	9		STRUCTURE	1
ODOMETER (km) (ENTER 9'S IF UNKNOWN) (ENTER 8'S IF ELECTRONIC) (ENTER 8'S IF ELECTRONIC)	8	(2) U (3) II	ODY & FRAME INITIZED NTEGRAL-STUB FRAME ODY & PLATFORM FRAME	63
NUMBER OF OCCUPANTS (ENTER 9'S IF UNKNOWN)	2 56	(5) P (7) C	E.G. VW BUG) PARTIALLY UNITIZED OTHER: INKNOWN	
TRAVELING SPEED (km/h) 9 9	9 59	, ,		
(000) PARKED OR STOPPED (995) JUST STARTING UP (996) BACKING UP (997) SPEED NOT EXCESSIVE (BUT UNKNOWN) (998) SPEED EXCESSIVE (BUT UNKNOWN) (999) UNKNOWN		(0) N (1) A (2) M	MISSION IONE UTOMATIC MANUAL INKNOWN	64
VEHICLE TYPE		LOCAT	ION OF TRANSMISSION	
PASSENGER VEHICLE (11) 2-DOOR HARDTOP (NO UPPER B-PILLAR) (12) 2-DOOR SEDAN OR COUPE	32	SELEC'	TOR LEVER LOOR	3
(ANY UPPER B-PILLAR) (13) 4-DOOR HARDTOP (14) 4-DOOR SEDAN (15) STATION WAGON (16) CONVERTIBLE (18) OTHER PASS. VEH. : (19) PASSENGER VEHICLE, TYPE UNKNOWN		(3) C (7) C	ONSOLE OLUMN OTHER: NKNOWN	65
MULTIPURPOSE PASSENGER VEHICLE (21) SMALL UTILITY (E.G. JEEP, SCOUT, BRONCO) (22) LARGE UTILITY (E.G. PANEL TRUCK, SUBURBAN)		STEER		
(22) VAN, SIZE UNKNOWN (23) VAN, SMALL (MINI) (25) VAN, LARGE (29) MPV, TYPE UNKNOWN (30) MOTOR HOME		(2) N	OWER IANUAL NKNOWN	86
TRUCK (31) PICKUP TRUCK, UNKNOWN (32) PICKUP TRUCK, SMALL (DOWNSIZED)		BRAKE	S OWER	
(33) PICKUP TRUCK, LARGE (99) UNKNOWN		(2) M	ANUAL NKNOWN	67

		VEHICLE DESCRIPTION VD-2
TYPE OF BRAKES (1) DRUM, ALL WHEELS (2) DISC, FRONT WHEELS (3) DISC, ALL WHEELS (9) UNKNOWN	3	WHEELBASE <i>(cm)</i> (999) Unknown
BRAKE ANTI-LOCK DEVICE (0) NONE INSTALLED (1) TWO-WHEEL (2) FOUR-WHEEL (7) EQUIPPED, UNKNOWN WHEELS (9) UNKNOWN AIR CONDITIONING IN VEHICLE (0) NO (1) YES (8) NOT COLLECTED (9) UNKNOWN	8 70	PLASTIC ANTI-LACERATIVE INNER LAYER GLASS EQUIPPED (0) NONE (1) WINDSHIELD (2) WINDSHIELD AND SIDE (7) OTHER (9) UNKNOWN
(9) UNINOWN TYPE OF DRIVE (1) REAR WHEEL (2) FRONT WHEEL (3) FOUR WHEEL (4) ALL WHEEL DRIVE (9) UNKNOWN DUAL REAR WHEELS (0) NO (1) YES (9) UNKNOWN	71	FIELD INVESTIGATOR INSTRUCTIONS: 1. INDICATE CRUSHED AREAS BY <u>OUT-LINING NEW PERIMETER</u> OF VEHICLE AND <u>SHADING THE DAMAGED AREAS</u> ON THE LARGE SKETCH ON PAGE VD-3. USE AS MANY SKETCHES AS NECESSARY TO COMPLETELY DESCRIBE THE DAMAGE. 2. ENTER THE DIMENSIONS ON THE SKETCH(ES) MEASURED TO THE POINT OF MAXIMUM PENETRATION BY THE
ORIGINAL TYPE OF RESTRAINT SYSTEM (1) ACTIVE BELT (2) PASSIVE BELT (3) AIRBAG (4) KNEE BOLSTERS (7) OTHER: (8) NOT APPLICABLE (NOT EQUIPPED) (9) UNKNOWN	3	OBJECT(S) CONTACTED. USE THE EXAMPLES BELOW AS A GUIDE. 3. ENTER THE THREE DIMENSIONS TO THE CENTER OF THE WHEELS (WHEELBASE, FRONT AND REAR OVERHANGS) ON BOTH SIDES OF THE CAR. 4. ADD OTHER DIMENSIONS AS NECESSARY TO COMPLETELY DESCRIBE THE DAMAGE. EXAMPLES:
EQUIPPED WITH ROLL BAR (0) NO (1) YES (9) UNKNOWN TYPE OF ROOF (0) NONE (1) SOLID (2) T-TOP CLOSED (3) T-TOP OPEN (4) SUN ROOF CLOSED (5) SUN ROOF OPEN (6) CONVERTIBLE CLOSED (7) CONVERTIBLE OPEN (8) OTHER:	74	FRONT OR REAR ROOF (REFERENCE TO TOP OF DOOR SILL OR WINDOW SILL)

Duplicate columns 1-8 from the previous card.

Module V D Format 0 2 11 12

VEHICLE DESCRIPTION

VD-3

ORIGINAL SPECIFICATIONS

Wheelba se	33	3 cm
Curb Weight Average Track Width	<u>18</u> <u>15</u>	09 kg
Overall Length	5 4	6 cm
Overall Width (OAW)	198	2 cm


Front Overhang

Rear Overhang


Undeformed End Width (UEW)

Engine Displacement

Engine: # of Cylinders



VEHICLE DAMAGE



FRONTAL CRASH OVERLAP

Round up for .5. 98 = 98% or more Enter % overlap or "99" for missing or N/A. Direct Damage Length (DDL)

 $\frac{1}{35} \frac{4}{4} \frac{5}{37}$ cm

Front-End Overlap (Percent) = DDL UEW

 $\frac{9}{38} \frac{8}{39} \%$

Vehicle Overlap (Percent) = <u>DDL + 1/2 (OAW - UEW)</u> OAW 9 8 %

	A_Format 0 2 11 12	DAMAGE DA-1
PRIMARY	CASE VEHICLE PRIMARY CDC	CONTACTED VEHICLE ASSOCIATED CDC
EVENT NUMBER	13	,
IMPACT SPEED (km/h)	$\frac{9}{14}\frac{9}{15}\frac{9}{16}$	$\frac{999}{35}$
ESTIMATED BY	$\frac{1}{2}$	1
CRUSH (cm)		$99^{38} - 940^{38}$
CDC #1	12.FDEW.4	99.00000
CDC #2	<u>98.0000</u> .00	9800000
	* above bumper	
Duplicate columns 1-8 Module D from the previous card. 9 10	A Format 0 3	
SECONDARY	CASE VEHICLE SECONDARY CDC	CONTACTED VEHICLE ASSOCIATED CDC
EVENT NUMBER	8 13	
IMPACT SPEED (km/h)	14 15 16	35 36 37
ESTIMATED BY		35 36 37
CRUSH (cm)	18 19 20	38
CDC #1		42
CDC #2	28 34	49
Codes	VA - WA	
EVENT NUMBER	IMPACT SPEED ESTIMATOR	CRUSH
(8) NOT APPLICABLI (9) UNKNOWN	(2) DRIVER	(998) NOT APPLICABLE (NO VEHICLE/DAMAGE)
IMPACT SPEED	(3) POLICE (4) "CRASH" PROGRAM	(999) UNKNOWN
(998) NOT APPLICAE (999) UNKNOWN	(5) OTHER COMPUTER PROGRAM SPECIFY: (7) OTHER: (8) NOT APPLICABLE (NO VEHICLE/NO IMPACT)	CDC (9800000) NOT APPLICABLE (9900000) UNKNOWN

Module <u>D</u> <u>A</u> Format <u>0</u> <u>1</u> 12 DAMAGE DA-2 Duplicate columns 1-8 from the previous card. MAXIMUM SHEET METAL CRUSH (999) UNKNOWN (cm) RIGHT SIDE REAR LEFT SIDE **ROOF OTHER** CHRONOLOGICAL SEQUENCE OF DAMAGE/INJURY PRODUCING CRASH EVENTS FOR CASE VEHICLE DO YOU KNOW THIS TABLE TO BE IN CHRONOLOGICAL ORDER? NOTE: IF CHRONOLOGICAL ORDER IS UNKNOWN, EVENT ORDER IS OPTIONAL. (0) NO (1) YES EVENT NUMBER IMPACT LOCATION **IMPACT OBJECT/VEHICLE** CONFIGURATION CONTACTED (1) ON ROADWAY (2) SHOULDER/MEDIAN/GORE FOR CODES, SEE TABLE FOR CODES, SEE TABLE (3) ON ROADSIDE ON PAGE DA-3. ON PAGE DA-4. (4) OUTSIDE ROADSIDE RIGHT-OF-WAY (5) OTHER (6) OFF ROADWAY, LOC. UNK. (9) UNKNOWN #1 #2 37 #3 #4 47 51 #5 52 #6 57 #7

CODES FOR IMPACT CONFIGURATION

FRONT OF CASE VEHICLE

- (11) AND FRONT OF CONTACTED VEHICLE
- (13) AND SIDE OF CONTACTED VEHICLE
- (14) AND REAR OF CONTACTED VEHICLE
- (16) ENDSWIPED BY CONTACTED VEHICLE
- (17) AND OBJECT
- (19) AND <u>UNKNOWN</u> OTHER VEHICLE CONFIGURATION

LEFT SIDE OF CASE VEHICLE

- (21) AND FRONT OF CONTACTED VEHICLE (TYPE T)
- (22) AND FRONT OF CONTACTED VEHICLE (TYPE L)
 (23) AND SIDE OF CONTACTED VEHICLE (NOT SIDESWIPE)
- (24) AND REAR OF CONTACTED VEHICLE (TYPE T)
- (25) AND REAR OF CONTACTED VEHICLE (TYPE L)
- (26) SIDESWIPED BY CONTACTED VEHICLE
- (27) AND OBJECT
- (29) AND UNKNOWN OTHER VEHICLE CONFIGURATION

REAR OF CASE VEHICLE

- (31) AND FRONT OF CONTACTED VEHICLE
- (33) AND SIDE OF CONTACTED VEHICLE
- (34) AND REAR OF CONTACTED VEHICLE
- (36) ENDSWIPED BY CONTACTED VEHICLE
- (37) AND OBJECT
- (39) AND UNKNOWN OTHER VEHICLE CONFIGURATION

RIGHT SIDE OF CASE VEHICLE

- (41) AND FRONT OF CONTACTED VEHICLE (TYPE T)
- (42) AND FRONT OF CONTACTED VEHICLE (TYPE L)
- (43) AND SIDE OF CONTACTED VEHICLE (NOT SIDESWIPE)
- (44) AND REAR OF CONTACTED VEHICLE (TYPE T)
 (45) AND REAR OF CONTACTED VEHICLE (TYPE L)
- (46) SIDESWIPED BY CONTACTED VEHICLE (47) AND OBJECT
- (49) AND UNKNOWN OTHER VEHICLE CONFIGURATION

OTHER

- (57) VEHICLE TO OBJECT
- (58) VEHICLE TO VEHICLE
- (59) VEHICLE TO VEHICLE, CONFIGURATION UNKNOWN

ROLLOVER

- (61) LESS THAN 360°
- (62) 360° OR MORE
- (69) DETAILS UNKNOWN

UNKNOWN

(99) IMPACT TYPE UNKNOWN

DAMAGE DA-4

CODES FOR VEHICLE/OBJECT CONTACTED

VEHICLE/OBJECT GROUPS

- NO OBJECT (00)
- (01) (39) PASSENGER VEHICLE & TRUCK
- (40) (69) OTHER VEHICLE
- (70) (76) PEDESTRIAN & ON-ROADWAY OBJECT
- (77) (97) OFF-ROADWAY OBJECT
- OTHER (DESCRIBE) (98)
- (99) UNKNOWN

PASSENGER VEHICLE

- (02) LARGE
- (03) LIMOUSINE
- (17) PICKUP
- (20) UNKNOWN PASSENGER VEHICLE BODY
- (24) SUB-MINI
- (25) MINI
- (26) SUB-COMPACT
- (27) COMPACT
- (28) INTERMEDIATE
- (29) FULL

WHEELBASE SIZE

< 2286 mm (< 90") SUB-MINI 2286 - 2412 mm (90" - 94.9") MINI 2413 - 2539 mm (95" - 99.9") SUB-COMPACT 2540 - 2666 mm (100" - 104.9") COMPACT 2667 - 2793 mm (105" - 109.9") INTERMEDIATE FULL 2794 - 2920 mm (110" - 114.9") 2921 - 3174 mm (115" - 124.9") LARGE

> 3175 mm (> 125") LIMOUSINE

MULTIPURPOSE PASSENGER VEHICLE

- (11) SMALL VAN (MINI)
- (12) PICKUP
- (14) SMALL UTILITY (WHEELBASE LESS THAN 107", E.G. JEEP, BRONCO)
- (15) LARGE UTILITY (WHEELBASE MORE THAN 107°, E.G. PANEL TRUCK, SUBURBAN)
- (16) PICKUP TRUCK WITH CANOPY/SHELL COVER
 (17) PICKUP CAR WITH CANOPY/SHELL COVER
- (21) MOTOR HOME
- (22) PICKUP TRUCK WITH SLIDE-IN CAMPER
- (23) PICKUP CAR WITH SLIDE-IN CAMPER
- (31) CHASSIS-MOUNTED CAMPER

TRUCK

- (11) SMALL VAN (E.G. ECONOLINE)
- (12) PICKUP TRUCK
- (13) UNKNOWN LIGHT TRUCK
- (15) LARGE UTILITY (E.G. PANEL TRUCK, SUBURBAN)
- (16) PICKUP TRUCK WITH CANOPY/SHELL COVER
- (22) PICKUP TRUCK WITH SLIDE-IN CAMPER
- (30) UNKNOWN TRUCK TYPE
- (31) CHASSIS-MOUNTED CAMPER
- (33) DELIVERY VAN (WALK-IN)
- (34) STRAIGHT TRUCK
- (35) TRUCK-TRACTOR (BOBTAIL)
- (36) CHASSIS-CAB
- (37) UNKNOWN HEAVY TRUCK
- (38) TRACTOR & SEMI-TRAILER (SEMI)
- (39) TRUCK (OR SEMI) & FULL TRAILER(S)

BUS

- (40) UNKNOWN BUS TYPE
- (41) SCHOOL BUS
- (42) INTERCITY BUS (BETWEEN CITIES)
- (43) TRANSIT BUS (INTRACITY)
- (44) STREETCAR (ON TRACKS)

MOTORCYCLE

- (50) UNKNOWN MOTORCYCLE TYPE

- (51) 1 75 cc (52) 76 125 cc (53) 126 250 cc
- (54) 251 500 cc (55) 501 - 750 cc
- (56) 751 cc +
- (57) 3-WHEELS (OR WITH SIDECAR)

SPECIAL PURPOSE VEHICLE

- (60) UNKNOWN/OTHER SPECIAL VEHICLE (DESCRIBE)
- (61) SNOWMOBILE
- (62) ATV (ALL TERRAIN VEHICLE)
- (63) AMPHIBIOUS VEHICLE
- (64) FARM VEHICLE
- (65) CONSTRUCTION VEHICLE
- (66) TRAILER, PRIVATE (CAMPER) (67) TRAILER, COMMERCIAL (CARGO) (68) TRAIN (CARS)

- (69) LOCOMOTIVE (ENGINE, SWITCHER)

OBJECT

- (70) PEDESTRIAN
- (71) BICYCLIST, OTHER PEDALCYCLIST
- (72) PEDESTRIAN CONVEYANCE (E.G. PERSON RIDING ANIMAL, CART)
- (73) LARGE ANIMAL
- (74) FALLEN OBJECT (E.G. OBJECT DISLODGED FROM OTHER VEHICLE, FALLEN TREE, ROCKS)
- (75) ROCKS
- (76) CONSTRUCTION EQUIPMENT (EXCLUDING (65))
- (77) SIGN POST, UTILITY POLE, TREE
- (78) DITCH
- (79) EMBANKMENT, SNOWBANK, RR TRACKS RR X
- (80) GROUND (ROLLOVER ONLY)
- (81) CURB (DAMAGE PRODUCING IMPACTS ONLY)
- (82) CULVERT
- (83) FENCE
- (84) HYDRANT, SHORT POST, STUMP
- (85) SMALL POST/TREE, RURAL MAIL BOX, MILE MARKER, DELINEATOR
- (86) BUILDING
- (87) PIER, PILLAR, BRIDGE SUPPORT
- (88) ABUTMENT, RETAINING WALL
- (89) BRIDGE RAIL
- (90) GUARD RAIL, LEADING SECTION

- (91) GUARD RAIL, LEADING SECTION
 (91) GUARD RAIL, MIDDLE OR UNKNOWN
 (92) GUARD RAIL, TRAILING SECTION
 (93) GUARD POST (TIMBER, METAL, CONCRETE)
- (94) CABLE, FENCE BARRIER
- (95) CONCRETE BARRIER (MEDIAN)
- (96) IMPACT ATTENUATOR
- (97) BREAKAWAY FEATURES

	R Format 0 1 12		H RECONSTRUCT	TION CR-1	
	CASE VEHICLE F	PRIMARY IMPACT	CONDARY IMPACT		
	CASE VEHICLE	CONTACTED VEHICLE	CASE VEHICLE	CONTACTED VEHICLE	
EVENT NUMBER	13		47		
ΔV (km/h) TOTAL	$\frac{9}{14} \frac{9}{15} \frac{9}{16}$	$\frac{9}{32} \frac{9}{33} \frac{9}{34}$	48 49 50	66 67 68	
LONGITUDINAL*	$\left \frac{9999}{7} \frac{99}{20} \right $	$\frac{9}{35} = \frac{9}{9} = \frac{9}{35}$	51 54	69 72	
LATERAL*	9999	9999			
NOTE: THESE ΔV COMPONENTS MUST INCLUDE SIGN.	21 24	39 42	55 58	73 76	
EXAMPLES: 10 km/h = ± <u>Q 1 Q</u> -7 km/h = <u>: Q Q 7</u>					
ENERGY DISSIPATED BY CRUSH (kg)	$\frac{99999}{25}$	9999	59 62	77 80	
RECONSTRUCTION					
(01) RECONSTRUCTED, UNKNOWN CONFIDENCE LEVEL	11				
(21) RECONSTRUCTED, LOW CONFIDENCE LEVEL (22) RECONSTRUCTED, MODERATE CONFIDENCE LEVEL (23) RECONSTRUCTED, HIGH CONFIDENCE LEVEL	29 30		63 64		
NOT RECONSTRUCTED BECAUSE					
(02) INSUFFICIENT DATA (03) EXCESSIVE UNDERRIDE/ OVERRIDE (04) ROLLOVER (05) VAULTING (06) OTHER TRAVEL IN MORE THAN ONE PLANE (07) NON-HORIZONTAL FORCE (08) SIDESWIPE-TYPE DAMAGE	* •				
(09) YIELDING OBJECT (10) OTHER: (11) AT LEAST ONE VEHICLE BEYOND SCOPE (12) OTHER VEHICLE NOT INSPECTED					
MODE					
(1) CDC ONLY (2) CDC & DETAILED DAMAGE (3) TRAJECTORY & CDC (4) TRAJECTORY & CDC & DETAILED DAMAGE (5) NOT RECONSTRUCTED	<u>5</u>		65		
COMPUTER PROGRAM SPECIFY:					

Duplicate columns 1-8 from the previous card. Module C F F F F F F F F F F F F F F F F F F	Format <u>0 2</u>		H RECONSTRUCT	TION CR-2
	CASE VEHICLE P	RIMARY IMPACT	CASE VEHICLE SE	CONDARY IMPACT
	CASE VEHICLE	CONTACTED VEHICLE	CASE VEHICLE	CONTACTED VEHICLE
EVENT NUMBER	13		47	
EBS (km/h) TOTAL		$\frac{9}{32}\frac{9}{33}\frac{9}{34}$	48 49 50	66 67 68
LONGITUDINAL*	$\frac{-}{17}$ $\frac{0}{5}$ $\frac{1}{20}$	$\frac{9}{35} = \frac{9}{9} = \frac{9}{38}$	51 54	
LATERAL*	+ 0 00	9999		
*NOTE: THESE EBS COMPONENTS MUST INCLUDE SIGN.	21 24	39 42	55 58	73 76
EXAMPLES: 10 km/h = ± <u>0</u> 1 <u>0</u> -7 km/h = <u>-</u> <u>0</u> <u>0</u> <u>7</u>				÷
ENERGY DISSIPATED BY CRUSH (kj)	$\frac{0}{25}$ $\frac{2}{4}$ $\frac{7}{28}$	9999	59 62	77 80
RECONSTRUCTION				
(01) RECONSTRUCTED, UNKNOWN CONFIDENCE LEVEL	21	,		
(21) RECONSTRUCTED, LOW CONFIDENCE LEVEL (22) RECONSTRUCTED, MODERATE CONFIDENCE LEVEL (23) RECONSTRUCTED, HIGH CONFIDENCE LEVEL	29 30		63 64	
NOT RECONSTRUCTED BECAUSE				
(02) INSUFFICIENT DATA (03) EXCESSIVE UNDERRIDE/ OVERRIDE (04) ROLLOVER (05) VAULTING (06) OTHER TRAVEL IN MORE THAN ONE PLANE (07) NON-HORIZONTAL FORCE (08) SIDESWIPE-TYPE DAMAGE (09) YIELDING OBJECT				
(10) OTHER: (11) AT LEAST ONE VEHICLE BEYOND SCOPE (12) OTHER VEHICLE NOT INSPECTED				
MODE (1) CDC ONLY (2) CDC & DETAILED DAMAGE (3) TRAJECTORY & CDC (4) TRAJECTORY & CDC & DETAILED DAMAGE (5) NOT RECONSTRUCTED	<u>2</u>		- 65	
COMPUTER PROGRAM SPECIFY: WINSMASS				÷

Duplicate columns 1-8 from the previous card.

Module <u>C</u> <u>R</u> Format <u>0</u> <u>3</u> 9 10 11 12

CRASH RECONSTRUCTION

CR-3

NOTES:

- 1. ENTER CRASH RECONSTRUCTION DAMAGE MEASUREMENTS IN CENTIMETERS.
- 2. MEASURE C $_1$ TO C $_6$ FROM DRIVER TO PASSENGER SIDE IN FRONT OR REAR IMPACTS, REAR TO FRONT IN SIDE IMPACTS.


CASE VEHICLE

LOCATOR

- 3. D IS POSITIVE IF MEASURED TO A POINT FORWARD OF OR TO THE RIGHT OF THE CG.
- 4. USE THE CENTER OF THE WHEELBASE AS THE CG.

Locate the end of the damage with respect to the vehicle longitudinal center line, or an undamaged axle for side impacts.

Specific Impact No.	Location of Direct Damage	Location of Field L
	Beyns (Dfront bumper corner	B.C. to B.C.
-		,



DL 145 UDL 5

PLANE:

- (1) Bumper
- (2) Above Bumper
- (3) SIII
- (4) Above Sill
- (5) Other _
- (9) Unknown

CRUSH PROFILE IN CENTIMETERS

NOTE: Each line in the table below is a separate record (card).

Duplicat

0	NOTE: Each	line in the tab	ole below is a	separate rec	ord (card).		plicate col	umns 1 - 1	2 for each	complete	d line.
Specific Impact Number	Plane of Impact C-Measur.	Direct Length (DDL)	Damage Max Crush	Field	C ₁	C ₂	C ₃	C ₄	C ₅	C ₆	±D
1	Bumper	145		145	41	27	24	23	29	49	Φ
					-11	-5	-0	-0	-5	-11	
					30	スコ	24	23	24	38	
*	Above bumpa	<u> </u>	94 est.		94	94	94	94	94	94	
	ave.				. 62	58	59	59	59	66	
1		145	094	145	O 62	Ø58	059	054	059	066	+000
13	14	15 16 17	18 19 20	21 22 23	24 25 26	27 28 29	30 31 32	33 34 35	36 37 38	39 40 41	42 43 44 45
			·								
							1	J 7	S. T.		
2											

Duplicate	columns 1-8
	previous card.

Module <u>C</u> <u>R</u> Format <u>0</u> <u>4</u>

CRASH RECONSTRUCTION

CR-4

NOTES:

- 1. ENTER CRASH RECONSTRUCTION DAMAGE MEASUREMENTS IN CENTIMETERS.
- 2. MEASURE C $_{\rm 1}$ TO C $_{\rm 6}$ FROM DRIVER TO PASSENGER SIDE IN FRONT OR REAR IMPACTS, REAR TO FRONT IN SIDE IMPACTS.

OTHER VEHICLE

LOCATOR

3. D IS POSITIVE IF MEASURED TO A POINT FORWARD OF OR TO THE RIGHT OF THE CG.

4. USE THE CENTER OF THE WHEELBASE AS THE CG.


Locate the end of the damage with respect to the vehicle longitudinal center line, or an undamaged axle for side impacts.


Specific Impact No.	Location of Direct Damage	Location of Field L
		·

Not Inspected. (trailer)

PLANE:

- (1) Bumper
- (2) Above Bumper
- (3) SIII
- (4) Above Sill
- (5) Other_
- (9) Unknown





DL _____

UDL ____

CRUSH PROFILE IN CENTIMETERS

		line in the tab	ole below is a s	separate reco	ord (card).	Dup	olicate colu	<u>ımns 1 - 1</u>	2 for each	completed	d line.
Specific Impact Number	Plane of Impact C-Measur.	Direct Length (DDL)	Damage Max Crush	Field L	C ₁	C ₂	C ₃	C ₄	C ₅	C ₆	±D
		, , , , , , , , , , , , , , , , , , , ,									
1											
13	14	15 16 17	18 19 20	21 22 23	24 25 26	27 28 29	30 31 32	33 34 35	36 37 38	39 40 41	42 43 44 45
			•								
											-
	,									-	
2					-						

Duplicate columns 1-8 Module W T from the previous card.			WHEELS AND TIRES WT-1
WHEELSDAMAGED (0) NO (1) YES (9) UNKNOWN	LF RF RR LR		SIZE (NOT DOT CODE. IF UNKNOWN, USE 9'S) LF $\frac{P}{25}$ $\frac{2}{4}$ $\frac{1575R15}{575R15}$ RF $\frac{P}{35}$ $\frac{2}{45}$ $\frac{1575R15}{575R15}$
TIRE TREAD TYPE (1) REGULAR (2) SNOW (3) SLICKS (4) ALL WEATHER (MS) (7) OTHER: (9) UNKNOWN	LF RF RR LR	4 17 4 4 4 2	LR Pals75R15_
CARCASS CONSTRUCTION (1) BIAS (2) BELTED BIAS (3) RADIAL (4) ELLIPTICAL (5) HI PRESSURE SPARE (6) SPACE SAVER SPARE (7) OTHER: (9) UNKNOWN	LF RF RR LR	3 3 3 3 24	
IF VEHICLE IS EQUIPPED WITH DUAL WHEELS, COMPLETE FOR OUTER WHEELS AND MAKE NOTES ON INNER WHEELS. NOTES:			

Duplicate columns 1-8 Module F T Format 0 from the previous card.	1 12	FUEL AND FUEL TANKS	FT-1
TYPE OF PROPULSIVE FUEL (1) GASOLINE (2) DIESEL OIL (3) LPG (4) ELECTRIC (7) OTHER: (9) UNKNOWN	13	AUXILIARY TANK TYPE (1) OEM TANK (2) AFTER MARKET TANK (8) NOT APPLICABLE (NOT EQUIPPED) (9) UNKNOWN	<u>8</u>
MAIN TANK LOCATION	1/12	AUXILIARY TANK LOCATION	882
MAIN FILLER CAP LOCATION	1 13	AUXILIARY FILLER CAP LOCATION	888
MAIN TANK MATERIAL	3	AUXILIARY TANK MÁTERIAL	8/28
(2) IN K (3) BET (4) FOF (8) NOT (9) UNK SECOND DI (1) LEF (2) WITI (3) RIGI (4) DUA (8) NOT (9) UNK THIRD DIGIT (1) BELL (2) WITI (3) ABO	WEEN KICKWARD OF APPLICATION OF FRAME HT OF FRAME APPLICATION OW FRAME HIN FRAME WE FRAME APPLICATION OW FRAME APPLICATION APPLICATION OW FRAME APPLICATION APPLICATION OW FRAME APPLICATION OF TRAME	K-UP & COWL COWL BLE (NOT EQUIPPED) RAL) ME E OR CENTERED ME & LEFT TANKS BLE (NOT EQUIPPED) AL) E E OR CENTERED	
TANK MATER (1) STEI (2) ALUI (3) PLAS (7) OTH (8) NOT (9) UNKI	EL MINUM STIC ER APPLICAB	DES BLE (NOT EQUIPPED)	

Duplicate	columns 1	-8
	previous ca	

Module F L Format 0 1 10

FUEL LEAKAGE FL-1

DID FUEL LEAKAGE RESULT FROM A CRASH EVENT

(0) NO KNOWN LEAKAGE SKIP PAGE.

(1) YES COMPLETE PAGE.



	l	II	Ш	IV	V	
LEAK NUMBER	LEAKING COMPONENT	COMPONENT SOURCE	TYPE OF DAMAGE	SEVERITY OF DAMAGE	LOCATION OF LEAK	EVENT NUMBER
#1	14 15			_	 ·	21
#2	22 23					29
#3	30 31			_		37
#4	38 39					45
#5	46 47			_		53

LEAKING COMPONENT

TANK AREA

- (11) MAIN FUEL TANK (INCLUDING VAPOR RECOVERY DOME)
- (12) AUXILIARY FUEL TANK
- (13) MAIN TANK FILLER TUBE
- (14) MAIN TANK CAP (GAS CAP)
- (15) AUXILIARY TANK FILLER TUBE
- (16) AUXILIARY TANK CAP (GAS CAP)
- (19) TANK AREA, DETAILS UNKNOWN

DELIVERY SYSTEM

- (21) FUEL FEED LINE (MAIN TANK TO FUEL PUMP)
- (22) FUEL FEED LINE (AUXILIARY TANK TO FUEL PUMP)
- (23) FUEL RETURN LINE (FUEL PUMP TO TANK)
- (24) INLINE FUEL FILTER
- (25) FUEL LINE (PUMP TO
- CARBURETOR OR INJECTOR PUMP) (26) CARBURETOR TO INJECTOR PUMP
- (27) FUEL PUMP
- (29) DELIVERY SYSTEM, DETAILS UNKNOWN

EVAPORATIVE EMISSION CONTROL SYSTEM

- (31) ATMOSPHERIC VENT PIPE (NON-EEC EQUIPPED)
- (32) EEC PIPE (VAPOR CANISTER TO CARBURETOR)

EEC SYSTEM (CONTINUED)

- (33) VAPOR RECOVERY HOSES (CANISTER TO CARBURETOR)
- (34) LIQUID-VAPOR SEPARATOR (UNLESS PART OF TANK)
- (35) CANISTER
- (39) EEC SYSTEM, DETAILS UNKNOWN
- (49) ENGINE COMPARTMENT, COMPONENT UNKNOWN
- (99) COMPONENT UNKNOWN

II COMPONENT SOURCE

- (1) OEM
- (2) AFTER MARKET
- (9) UNKNOWN

III TYPE OF DAMAGE

- (1) DENTED/CRUSHED
- (2) PUNCTURED
- (3) RUPTURED
- (4) SEVERED/GROSS TEARS
- (5) DISCONNECTED/DEFEATED
- (9) UNKNOWN

IV SEVERITY OF DAMAGE

- (1) MINOR
- (2) MODERATE
- (3) SEVERE
- (4) DISCONNECTED/DEFEATED
- (9) UNKNOWN

V LOCATION OF LEAK

FIRST DIGIT (LONGITUDINAL LOCATION)

- (1) F, FORWARD OF COWL
- (2) P, BETWEEN COWL & REAR BULKHEAD
- (3) B, BEHIND REAR BULKHEAD
- (4) Y, F, & P
- (5) Z, P, & B
- (6) D, DISTRIBUTED (F, P & B)
- (9) UNKNOWN

SECOND DIGIT (LATERAL LOCATION)

- (1) L, LEFT
- (2) C, CENTER
- (3) R, RIGHT
- (4) Y, LEFT CENTER (L & C)
- (5) Z, RIGHT CENTER (R & C)
- (6) D, DISTRIBUTED
- (F, P & B) (9) UNKNOWN

Duplicate columns 1-8 Module F R Format 0 from the previous card. 9 10 11		FIRE	FR-1
WAS THERE FIRE IN (0) NO <u>SKIP</u> PAC (1) YES <u>COMPLE</u>	GE.	CASE VEHICLE?	
DID FIRE START IN CASE VEHICLE? (0) NO (1) YES (9) UNKNOWN	14	SEVERITY OF FIRE DAMAGE (1) MINOR (2) MODERATE (3) SEVERE (9) UNKNOWN	16
FLAME PROPOGATION RATE (1) RAPID/EXPLOSIVE (2) SLOW/MODERATE (9) UNKNOWN	15	DID AN INJURY TO CASE VEHICLE OCCUPANT RESULT FROM FIRE IN OR ON CASE VEHICLE? (0) NO (1) YES (9) UNKNOWN	17

PROVIDE NOTES IF FIRE OCCURRED.

Duplicate columns 1-8 from the previous card.		E D Format	EXTERIOR DAMAGE	ED-1
HOOD PERFORM	1ANCE		STEERING COL FLEXIBLE COUP	
				LING
FOR THE FOLLOW	'ING, USE CC	DDES:	FLEXIBLE COUPLING TYPE	
(0) NO			(0) NONE (1) FLEXIBLE MATERIAL (2) POT	9 26
(1) YES (8) NOT APPLI	CABLE		(3) SINGLE U-JOINT (4) DOUBLE U-JOINT	
(9) UNKNOWN			(5) FLEXIBLE CABLE (6) COMBINATION OF ABOVE	
11000 1 1501 (50)			(CIRCLE EACH) (7) OTHER:	
HOOD LATCH <i>(ES)</i> -		-RELEASED	(8) EQUIPPED, TYPE UNKNOWN (9) UNKNOWN, IF EQUIPPED	
		-DAMAGED	A = A = A	
			COUPLINGDAN	IAGED 9
		-JAMMED	15 FROM HOOD	
				ARATED 9
HOOD HINGES-	-LEFT,	DAMAGED	16	= 2.2)
	-LEFT,	SEPARATED	Q	
	-RIGHT,	(COMPLETE) DAMAGED	ENG COMPART TELESCOPING U	
	,	DAMAGED	18	NIT
	-RIGHT,	SEPARATED (COMPLETE)	TYPE OF UNIT	
		(00,111, 22,12)	(01) - (07) SEE UNITS ON PAGE ED-2	
HOOD REMAINED ON VEHICLE			(88) NOT COLLECTED (97) OTHER: — (98) EQUIPPED, TYPE UNKNOW	29 30
			(98) EQUIPPED, TYPE UNKNOW (99) UNKNOWN IF EQUIPPED	'N
REAR EDGE OF HOO	OD.	-ELEVATED		
		LLEVATED	ORIGINAL LENGTH (mm)	
-C	ONTACTED	WINDSHIELD	F (OR H):	
-Pi	ENETRATED	WINDSHIELD	TELESCOPED LENGTH (mm)	
			G:	
HOOD LATCH LOCAT	TON		. 1	
(1) FRONT OF VE (2) COWL AREA	HICLE		DIFFERENCE (mm)	0
(3) SIDE (8) NOT APPLICA	RIF		F (OR H) - G	
(9) UNKNOWN			(IF LESS THAN 15mm, ENTER "000".)	
			(888) NOT COLLECTED (991) NOT MEASURED/NO	
Engine or Trans	MISSION	Mount	COMPRESSION (992) COMPRESSED, AMOUNT	8 8
SEPARATION (COMP	PLETE)		UNKNOWN (993) DEVICE EXTENDED	31 :
(0) NO			(997) UNABLE TO BE MEASURED (998) NOT APPLICABLE (NOT	
(1) YES (9) UNKNOWN			EQUIPPED) (999) UNKNOWN	

		Exterior Damage	ED-2
LEFT-SIDE BODY MOUNT DID BODY MOUNT SEPARATE? (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	<u>Ø</u>	LEFT DOORS HOW DID DOORS OPEN DURING COLLISION?	
LEFT PILLARS PILLARS SEPARATED COMPLETELY - USE CODES: (0) NO (1) YES (4) NO SEPARATION, BUT DAMAGED (8) NOT APPLICABLE (NOT EQUIPPED) (9) UNKNOWN	Ø	USE CODES: (0) DOOR DID NOT OPEN OPENED BECAUSE OF (1) HINGE AREA SEPARATION (2) DOOR-LATCH SEPARATION (3) LATCH-STRIKER SEPARATION (4) STRIKER-PILLAR SEPARATION (5) BODY DISTORTION (6) COMBINATION OF ABOVE (CIRCLE EACH) (7) OPENED, REASON UNKNOWN (8) NOT APPLICABLE (NO DOOR)	
-A-PILLAR, UPPER LOWER -B-PILLAR, UPPER		(9) UNKNOWN -FRONT -REAR	Ø 2 8 1 4
LOWER	37 23 38	DOORS JAMMED CLOSED- USE CODES: (0) NO (1) YES (8) NOT APPLICABLE (NO DOOR)	
-C-PILLAR, UPPER LOWER	39 <u>8</u> 40	(9) UNKNOWN -FRONT -REAR	\$\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
-D-PILLAR, UPPER LOWER	\$ ₹ \$ \$ \$ \$		

		EXTERIOR DAMAGE	ED-3
REAR DOOR REAR DOOR TYPE (0) NO DOOR (INCLUDES PICKUPS) (1) HATCHBACK (2) ONE-WAY TAILGATE (3) TWO-WAY TAILGATE (4) CLAMSHELL/DISAPPEARING TAILGATE (5) SINGLE DOOR (6) DOUBLE DOOR (9) UNKNOWN Hatchback One-way	Ф	OTHER REAR DAMAGE WAS PARTITION TO LUGGAGE AREA DAMAGED DURING COLLISION? (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN SPARE TIRE (0) NO SPARE TIRE (1) NOT ATTACHED BEFORE COLLISION (2) ATTACHED, NOT SEPARATED IN COLLISION (3) ATTACHED, SEPARATED DUE TO COLLISION (6) NOT COLLECTED (9) UNKNOWN	8 51
Two-way Clamshell Single door Double door		TRAILER HITCH TYPE (0) NO HITCH BALL-AND-SOCKET TYPES (1) TEMPORARY FRAMEWORK (E.G. RENTAL CLAMP-ON) (2) BUMPER-MOUNT ONLY (E.G. LIGHT TRUCK) (3) BUMPER-AND-FRAME (BUT NON-EQUALIZING) (4) LOAD EQUALIZING OTHER TYPES (5) RING-AND-PINTLE (6) FIFTH-WHEEL (INCL. PU)	52
HOW DID DOOR OPEN DURING COLLISION? (0) DOOR DID NOT OPEN OPENED BECAUSE OF (1) HINGE AREA SEPARATION (2) DOOR-LATCH SEPARATION (3) LATCH-STRIKER SEPARATION (4) STRIKER-PILLAR SEPARATION (5) BODY DISTORTION (6) COMBINATION OF ABOVE (CIRCLE EACH) (7) OPENED, REASON UNKNOWN (8) NOT APPLICABLE (NO DOOR) (9) UNKNOWN DOOR JAMMED CLOSED (0) NO (1) YES (8) NOT APPLICABLE (NO DOOR) (9) UNKNOWN	8 48	(7) OTHER (E.G. CLEVIS-AND-PIN) (8) EQUIPPED, TYPE UNKNOWN (9) UNKNOWN IF EQUIPPED TRAILER TYPE (AT TIME OF COLLISION) (0) NO TRAILER (1) TRAVEL-TRAILER/CAMPER (2) MOBILE HOME (3) BOAT/SNOWMOBILE/ATV TRAILER (4) UTILITY TRAILER (5) TOWED CAR (7) OTHER: (8) TRAILER, TYPE UNKNOWN (9) UNKNOWN	53

	T	EXTERIOR DAMAGE E	D-4
RIGHT-SIDE BODY MOUNT DID BODY MOUNT SEPARATE? (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	54	RIGHT DOORS HOW DID DOORS OPEN DURING COLLISION? USE CODES:	
RIGHT PILLARS PILLARS SEPARATED COMPLETELY - USE CODES: (0) NO (1) YES (4) NO SEPARATION, BUT DAMAGED (8) NOT APPLICABLE (NOT EQUIPPED) (9) UNKNOWN		(00) DOOR DID NOT OPEN OPENED BECAUSE OF (01) HINGE AREA SEPARATION (02) DOOR-LATCH SEPARATION (03) LATCH-STRIKER SEPARATION (04) STRIKER-PILLAR SEPARATION (05) BODY DISTORTION (06) COMBINATION OF ABOVE (CIRCLE EACH) (07) OPENED, REASON UNKNOWN (11) VAN RIGHT-REAR DOOR OPENED (ANY MECHANISM)	
-A-PILLAR, UPPER	<u>S</u>	(98) NOT APPLICABLE (NO DOOR) (99) UNKNOWN -FRONT	<u> </u>
LOWER		-REAR	$\frac{9}{65}$
LOWER	57	DOORS JAMMED CLOSED- USE CODES: (0) NO	
-C-PILLAR, UPPER	♦	(1) YES (8) NOT APPLICABLE (NO DOOR) (9) UNKNOWN	1
LOWER	8	-FRONT -REAR	8
-D-PILLAR, UPPER	8 61	- Hand	68
LOWER	8 62	VAN REAR DOOR TYPE (0) VAN, NO REAR DOOR (1) TRACK (SLIDING) - RIGHT SIDE (2) SINGLE-HINGED - RIGHT SIDE (3) DOUBLE-HINGED - RIGHT SIDE (4) TRACK (SLIDING) - RIGHT & LEFT SIDE (5) SINGLE-HINGED - RIGHT & LEFT SIDE (6) DOUBLE-HINGED - RIGHT & LEFT SIDE	69
		(7) TRACK AND HINGED COMBINATION (8) NOT APPLICABLE (NOT A VAN) (9) UNKNOWN	

		EXTERIOR DAMAGE	ED-5
WINDSHIELD DAMAGE		WINDSHIELD MARK ON CASE VEHICL	E:
WINDSHIELD CRACKED (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	70		
WINDSHIELD BROKEN (PLASTIC INTERLAYER TORN) (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	71		
CRACKED OR BROKEN BY OCCUPANT CONTACT (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN EXTENT OF BOND SEPARATION (0) NONE (1) 1-20% (2) 21-40 (3) 41-60 (4) 61-80 (5) 81-99 (6) TOTAL (7) SEPARATED, AMOUNT UNKNOWN (8) NOT APPLICABLE (9) UNKNOWN	$\frac{1}{72}$ $\frac{1}{72}$	WINDSHIELD CODE (97) DESCRIBED BUT NOT CODED (98) NOT APPLICABLE (NO WINDSHIELD) (99) UNKNOWN ROOF DID T-ROOF/SUN ROOF OPEN DURING COLLISION? (0) NO (1) YES (8) NOT APPLICABLE (NOT A T-ROOF OR SUN ROOF) (9) UNKNOWN	9 9 74 75 8 76
LOCATE AREA OF WINDSHIELD INT & HORIZONTAL) ON THIS DIAGRAI	EREST OF MOF THE	R DAMAGE WITH DIMENSIONS (VERTICAL WINDSHIELD AS VIEWED FROM INSIDE.	Occul Conti


Timege from 14 contact w/ hood 14 contact w/ hood R


Duplicate columns 1-8 from the previous card. Module S C Format 9 10	0 1	STEERING WHEEL AND COLUMN	SC-1
STEERING WHEEL		STEERING WHEEL POSITION AT TIME OF COLLISION	
STEERING WHEEL RIM DAMAGE (0) NONE (1) DEFORMED SLIGHTLY (2) SEVERELY BENT (3) BROKEN (9) UNKNOWN	13	IN WHAT O'CLOCK POSITION WAS THE NORMAL TOP OF THE WHEEL POINTED WHEN THE COLLISION OCCURRED? EXAMPLES O'CLOCK = 1 2 O'CLOCK = 0 2	
NUMBER OF STEERING WHEEL SPOKES (9) UNKNOWN	4	(NORMAL STRAIGHT O'CLOCK 99	
STEERING WHL SPOKE DAMAGE (0) NONE (1) DEFORMED SLIGHTLY (2) SEVERELY BENT (3) BROKEN (9) UNKNOWN	15	STEERING WHEEL ENERGY ABSORBING DEVICE (1) EXAMPLES: BARRACUDA, 70 - 74 CHALLENGER, 70 - 74 CAPRI, 71 - 77	
STEERING COLUMN OPTIONS		(2) EXAMPLES: OMNI, 78 - HORIZON, 78 -	÷
TILT FEATURE (0) NOT EQUIPPED (1) YES, EQUIPPED, UNK POSITION (2) UP (3) MIDDLE (4) LOWER (9) UNKNOWN IF EQUIPPED	16	TYPE OF DEVICE (0) NONE (1) CONVOLUTED OR MESH CYLINDER (2) DEEP DISH STEERING WHEEL (7) OTHER: (8) NOT COLLECTED (9) UNKNOWN IF EQUIPPED	8 19
SWING-AWAY FEATURE (0) NOT EQUIPPED (1) YES, EQUIPPED (9) UNKNOWN IF EQUIPPED	<u>Ø</u>	ORIGINAL DIMENSION (mm) A: DAMAGE DIMENSION (mm) B:	
TELESCOPING FEATURE (0) NOT EQUIPPED (1) YES, EQUIPPED (9) UNKNOWN IF EQUIPPED	18	DIFFERENCE (mm) A - B (888) NOT COLLECTED (991) NOT MEASURED/NO APPARENT COMPRESSION (992) COMPRESSED, AMOUNT UNKNOWN (993) DEVICE EXTENDED (997) UNABLE TO MEASURE (998) NOT APPLICABLE (NOT EQUIPPED) (999) UNKNOWN	8 8

		STEERING WHEEL AND COLUMN	SC-2
STEERING COLUMN		STEERING WHEEL (CONTINUED)	
Energy Absorbing Device			
TYPE OF DEVICE * (IF 27 OR 28)		STEERING WHEEL HUB DAMAGE	
(00) NOT EQUIPPED (88) NOT COLLECTED (99) UNKNOWN	8 8 24	(1) OCCUPANT CONTACT (2) AIRBAG	Φ
ORIGINAL LENGTH (mm)		(3) OTHER	
C:			
COMPRESSED LENGTH (mm)			
D:			
BRACKET DEFLECTION (IF CODE 36, 48, OR 49 ABOVE) OR			
COMPRESSION (OR EXTRUSION) (mm)			
C - D (OR E) (TOLERANCE: ±10)			
(888) NOT COLLECTED (991) NOT MEASURED/NO APPARENT COMPRESSION (992) COMPRESSED, AMOUNT UNKNOWN (993) DEVICE EXTENDED (997) UNABLE TO BE MEASURED (998) NOT APPLICABLE (NOT EQUIPPED) (999) UNKNOWN	8 8 8 27	=	
* (ADD A & B FOR TOTAL COMPRESSION)			
SHEAR CAPSULE SEPARATION (mm)	8		
S (USE AVG. OF LEFT & RIGHT CAPSULES.)			
LT:			
RT:			
(888) NOT COLLECTED (991) NOT MEASURED/NO APPARENT SEPARATION (992) SEPARATED, AMOUNT UNKNOWN (997) UNABLE TO BE MEASURED (998) NOT APPLICABLE (NOT EQUIPPED) (999) UNKNOWN	8 8 8		
COLUMN VERTICAL ROTATION	į		
(0) NO APPARENT ROTATION (1) UPWARD APPARENT ROTATION (2) DOWNWARD APPARENT ROTATION (9) UNKNOWN	$\Phi_{\frac{1}{3}}$	2 1	
COLUMN LATERAL ROTATION			
(0) NO APPARENT ROTATION (1) LEFT APPARENT ROTATION (2) RIGHT APPARENT ROTATION (9) UNKNOWN	32		


									Intr	USION	IT-1
Location Intrusion	n of on	Intrude	d Compo	nent	Compar Valu		ements Are in Intruded Value	Centimete	Intrusion		Dominant Crush Direction
11		Instr	ment	×~el	140) –	121	=	19	re	arward
12		ų		ל	140) –	117	=	23		1/
13		٠,		••	138	_	130	=	8		t,
						_		=			
								=			-
	,					_		=			
								=			
								=			
								=			
								=	*		
								=			
								=			
								=			
								=			
								=			
ww	et ga espacea	en agranda en		jūlečekos s			Colored transport selections	=			
				00	CCUPANT C	ONTACT	WORKSHE	ET			
Contact	Co	nterior mponent ontacted	Occup No. i Know	f	Body Region if Known	S	Supporting F	^o hysical	Evidence		Confidence Level of Contact Point
Α	Rea	r view win	ur 1		had	Broken	of mo	untina	slate		1
В	1 .	shield	2		hend		nd hair				1
С	A-pil	lar mountail	<u> </u>		hend	l.	٠. •	•)
D	Glov	6 pox	2		Knee	Scoff	-mark		_		(
E	Inst P	rument and	1		Chest	h	٠				į
F		rShift	1		arm	bent					3
G											
Н											
ı				\perp							
J					·						







Chewed food Spattered over front of vehicle



CODES FOR COLUMN B, OCCUPANT SPACE NUMBER

OCCUPANT SPACE NUMBER IS A TWO-DIGIT CODE. THE USE OF THE CODE IS DETERMINED BY THE VEHICLE SEAT CONFIGURATION AT THE TIME OF THE ACCIDENT.

FIRST DIGIT

THE FIRST DIGIT (LEFT DIGIT) DENOTES THE SEAT ROW, WITH CODE VALUES FROM 1 TO 5.

SECOND DIGIT

THE SECOND DIGIT (RIGHT DIGIT) DENOTES THE POSITION ON THE SEAT AND, IN SOME INSTANCES, THE WIDTH OF THE SEAT.

(1) LEFT	(3) RIGHT		INDIVIDUAL SEAT
(1) LEFT	(2) CENTER	(3) RIGHT	. BENCH: FULL WIDTH 3 PASSENGER
(1) LEFT	(2) LEFT CENTER	(6) RIGHT (3) RIGHT CENTER	BENCH: FULL WIDTH 4 PASSENGER
(1) LEFT	(2) CENTER	(5) RIGHT &AISLE SPACE	BENCH: PARTIAL WIDTH, LEFT
(0) LEFT 8	(2) CENTER	(5) RIGHT &SPACE	BENCH: PARTIAL WIDTH, CENTERED
(4) ENTIR	VEHICLE WIDTH	4	CARGO AREA

EXAMPLES

THE TWO FIGURES BELOW PROVIDE EXAMPLES OF THE OCCUPANT SPACE NUMBER.

PASSENGER CAR 5 PASSENGERS

VAN 12 PASSENGER CAPACITY

X	X	11			13	
x x	X			21	22	25
x x	X			31	32	<i>3</i> 5
x x	x x	41	42	46	43	

CODES FOR COLUMN F, MEASUREMENT AXIS

(X) X-AXIS (FORE & AFT)

(Y) Y-AXIS (LATERAL)

(Z) Z-AXIS (VERTICAL)

CODES FOR COLUMNS G, H, I & J, OCCUPANT & INJURY NUMBERS

OCCUPANT NUMBER	INJURY NUMBER	CONTACT
(00)	(00)	NO CONTACT
(##)	(00)	CONTACT, NO INJURY
(97)	(99)	CONTACT, OCCUPANT UNKNOWN, INJURY UNKNOWN
(99)	(00) OR (99)	UNKNOWN IF CONTACT

CODES FOR COLUMN C, INTRUDING COMPONENT OR OBJECT

NOTE: DO NOT CODE OBJECTS OTHER THAN COMPONENTS OF CASE VEHICLE.

INDIVIDUAL COMPONENT

INTERNAL

(01) INSTRUMENT PANEL

(02) FIRE WALL

(03) TOE PAN (04) FLOOR PAN

(05) STEERING COLUMN

(06) WINDSHIELD

(07) WINDSHIELD HEADER

(08) A-PILLAR

(09) DOOR PANEL OR SIDE PANEL

(10) WINDOW FRAME

(11) B-PILLAR

(12) C-PILLAR

(13) D-PILLAR

(14) ROOF SIDE RAILS

(15) ROOF OR CONVERTIBLE TOP

(16) BACKLIGHT HEADER

(17) FRONT SEAT-BACK SURFACE/ SEAT-BACK BACK SURFACE

(18) SECOND SEAT-BACK SURFACE SEAT-BACK BACK SURFACE

(19) THIRD SEAT-BACK SURFACE SEAT-BACK BACK SURFACE

(20) FOURTH SEAT-BACK SURFACE SEAT-BACK BACK SURFACE

(21) FIFTH SEAT-BACK SURFACE SEAT-BACK BACK SURFACE

(22) BACK PANEL/BACK DOOR SURFACE

(23) SEAT CUSHION SURFACE/EDGE

(24) CONSOLE

(25) OTHER (DESCRIBE)

(26) UNKNOWN INTERNAL SURFACES

(28) TRANSMISSION TUNNEL (HUMP)

(29) SIDE FOOTWELL PANEL (KICKPANEL)

(30) SILL

EXTERNAL

(43) HOOD

(44) OBJECT EXTERNAL TO PASSENGER COMPARTMENT BUT PART OF CASE VEHICLE

(45) OUTSIDE SURFACE OF CASE VEHICLE

(46) OTHER (E.G. SPARE TIRE, JACK. DESCRIBE.)

(49) UNKNOWN EXTERNAL OBJECT

GROUPED FOR MASSIVE INTRUSION INTO AN OCCUPANT SPACE

USE ONLY IF ALL THESE COMPONENTS INTRUDED INTO A SINGLE OCCUPANT SPACE.

(50)WINDSHIELD HEADER A-PILLAR

ROOF SIDE RAIL

(51)INSTRUMENT PANEL A-PILLAR DOOR PANEL

(52)INSTRUMENT PANEL

A-PILLAR WINDSHIELD HEADER

(53)DOOR PANEL **B-PILLAR ROOF RAIL**

(54)DOOR PANEL A-PILLAR

ROOF RAIL (55)INSTRUMENT PANEL FLOOR PAN

> A-PILLAR DOOR FRAME

(56) ROOF RAIL A-PILLAR

B-PILLAR

WINDOW FRAME

(57)ROOF RAIL

A-PILLAR **B-PILLAR**

C-PILLAR DOOR PANEL

(58)ROOF

ROOF RAIL WINDOW FRAME DOOR PANEL

(59)BACKLIGHT HEADER

ROOF C-PILLAR

THIRD SEAT-BACK

(60)ROOF **ROOF RAIL** A-PILLAR **B-PILLAR** C-PILLAR

WINDOW FRAME DOOR PANEL FLOOR PAN

(61)INSTRUMENT PANEL **TOE PAN**

WINDSHIELD HEADER

A-PILLAR **ROOF RAIL** WINDOW FRAME DOOR PANEL

ROOF

(62)ROOF **ROOF RAIL** C-PILLAR

WINDOW FRAME FLOOR PAN

SECOND SEAT

DOOR PANEL

(63)ROOF RAIL ROOF

B-PILLAR WINDOW FRAME

FLOOR PAN

DOOR PANEL SECOND SEAT

FRONT SEAT

(64)ROOF RAIL

ROOF OR CONVERTIBLE TOP A-PILLAR

B-PILLAR

WINDOW FRAME

WINDOW HEADER

(65)WINDSHIELD WINDSHIELD HEADER

ROOF SIDE RAIL (66)WINDSHIELD

WINDSHIELD HEADER A-PILLAR

(98)NOT APPLICABLE

(99)UNKNOWN

Duplicate columns 1-8 from the previous card.	Module <u>I</u>	T Format 0	1 12			INTR	USION	T-5	
WAS THERE OCCUPA (0) NO <u>DO NOT</u> ANS (1) YES <u>ANSWER</u> NE (9) UNKNOWN <u>SKIE</u>	SWER NEXT QUEXT QUEXTION.	JESTION. <u>SKIP PA</u>	-) 13		ON CATAST COMPLETE PAC SKIP PAGE.		<u>Ø</u>	
		B, F, G, H, I, C C <i>on page it-</i>		1T-3	OCCUPANT	CONTACT A	ND INJURY		
	C C RUDING ASS PONENT EVE OBJECT NO	OC. MAXIMUM ENT INTRUSION	F MAXIMUM INTRUSION Y AXIS (cm)	G MAXIMUM INTRUSION Z AXIS (cm)	H OCCUPANT NUMBER	I INJURY NUMBER	J OCCUPANT NUMBER	K INJURY NUMBER	
13-14 15-16	17-18 19	9 20-21	22-23	24-25	26-27	28-29	30-31	32-33	
01 11 0	<u> </u>	19	QQ	ΦΦ	$\Phi\Phi$	ΦΦ	ΦΦ	Q Q	
	<u> </u>	23	Q Q	00	$\underline{\Phi}\underline{\Phi}$	Φ	$\underline{\Phi}\underline{\Phi}$	$\Phi \Phi$	
os 13 u	<u>) </u>	<u> </u>	ΦΦ	00	02	05	02	06	
<u> 0 4 </u>									
0 5									
06									
O 7. — — — NOTE: USE ADDITIONAL PAGE	 IF MORE THAN 7	 INTRUSIONS.							
Duplicate columns 1-8 from the previous card.		T Format 0	_3 12				*		
NOTE: IF NO SIDE DOOR INT SKIP REMAINDER OF I SIDE DOOR INTRU RESULTED FRO	PAGE. SION	IF DA DOO	R INTRUS	DOOR CO	OMPONENT E COMPONI	ENT	D IN INCRE	EASED	
INTRUSION		NUMB	ER CO	OMPONENT 1	СОМРО		CODES FOR COMPONE	ENTS	
FOR 0	DES CAUSE:	A	_		2	5	(0) NONE (1) A-PILLAR (2) B-PILLAR (3) C-PILLAR		
16 18 (2) IN	MPACT NDUCED DAMAGE	26 27 C	_		-	9 	(4) LATCH/STR (5) HINGES (7) OTHER:		
19 21 (9) U	NKNOWN	D	_		3		(8) NOT APPLI (9) UNKNOWN	CABLE	

Duplicate columns 1-8 from the previous card.

INTRUSION

IT-6

NOTE: Each line in the table below is a separate record (card).

Duplicate columns 1 - 12 for each completed line.

-- ADDITIONAL PAGE --

INTRUSIONS CODE INTRUSIONS IN THIS ORDER: LEFT TO RIGHT ON ROW; FRONT TO BACK IN VEHICLES. CODES FOR B, F, G, H, I, J ON PAGE IT-3 CODES FOR C ON PAGE IT-4 OCCUPANT CONTACT AND INJURY

A INTRUSION NUMBER	B OCC. SPACE NO.	C INTRUDING COMPONENT OR OBJECT		E MAXIMUM INTRUSION X AXIS (cm)	F MAXIMUM INTRUSION Y AXIS (cm)	G MAXIMUM INTRUSION Z AXIS (cm)	H OCCUPANT NUMBER	I INJURY NUMBER	J OCCUPANT NUMBER	K INJURY NUMBER
13-14	15-16	17-18	19	20-21	22-23	24-25	26-27	28-29	30-31	32-33
0.8										
0 9										
10										
11										
1 2										
13										
14			_							
15			_							
16		 .								
17										
18										
19										
20										
21									-	
2 2										
23										
24			 .							
2 5										
										


Duplicate columns 1-8 from the previous card.	Modu	ele <u>I</u> D 9 10	Format <u>0</u> <u>1</u> 12	ln ———	TERIOR DAMAGE	ID-1
	(1	D) NO I) YES B) NO, and	(8)	ES, and (NOT APPL		
SIDES FRONT DOOR FRONT HARDWARE FRONT ARMREST FRONT GLASS REAR DOOR AREA REAR HARDWARE REAR ARMREST REAR GLASS ROOF SIDE RAIL B-PILLAR C-PILLAR D-PILLAR HEADLINING ROOF STRUCTURE T-ROOF/SUN ROOF			FRONT FOOT CONTROLS IGNITION KEYS REAR VIEW MIRROR MISSING From vehicle SUNVISOR/FITTINGS (5) LEFT SIDE ONLY (6) RIGHT SIDE ONLY (7) BOTH SIDES WINDSHIELD TOP MOLDINGS LEFT A-PILLAR (UPPER OR LOWER) RIGHT A-PILLAR (UPPER OR LOWER) CENTER CONSOLE TRANSMISSION SELECTOR LEVER RIM, HORN, SPOKE	0 4 0 4 0 5 0 5 0 5 0 5 0 5 0 5 0 5 0 5	INSTRUMENT PANEL UPPER PANEL MID PANEL LOWER PANEL ASHTRAY CONTROL KNOBS & LEVERS GLOVE COMPARTMENT AREA INSTRUMENTS PARKING BRAKE RELEASE PARKING BRAKE PEDAL A/C OR UPPER VENT OUTLET HEATER OR A/C DUCTS RADIO OTHER: * Hand-hold mounted on right upper A-pillar	
OTHER: *	38 48 43 43	\$ <u>\$</u>			REAR WINDOW WINDOW HEADER	Q
*					CONSOLES VERTICAL ROOF	8 × × ×

Duplicate columns 1-8 from the previous card. Module S T 10) <u>2</u> 1 12	SEATS		ST-1
FRONT SEAT TYPE OF FRONT SEAT (00) NO SEAT (01) STANDARD BENCH (02) SPLIT BACK, 50-50 (03) SPLIT BACK, DRIVER WIDE (04) SPLIT BACK, PASS. WIDE (05) BUCKET (06) CAPTAIN'S CHAIR (07) INDIV. BENCH, 50-50 (08) INDIV. BENCH, DRIVER WIDE (09) INDIV. BENCH, PASS. WIDE	DRIVER DRIVER	PASSENTR 0 5 15 16	FRONT SEAT-BACK SEAT-BACK TYPE (1) FORWARD FOLDING (2) RIGID (3) RECLINING (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN	DRIVER 3	PASSENT 3
(97) OTHER: (99) UNKNOWN TYPE OF SEAT MOUNT (1) STANDARD (2) PEDESTAL (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN	17	18	SEAT-BACK LOCK TYPE (0) NONE (1) MANUAL (2) INERTIA (3) POWER (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN	32	33
SWIVEL MECHANISM EQUIPPED (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	<u>Ø</u>	20	LOCKS HELD (0) NO (1) YES (8) NOT APPLICABLE	34	35
ORIGINAL EQUIPMENT SEATS (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN CONTACT OF SEAT BY REAR OCCUPANT (0) NO (1) YES (8) NOT APPLICABLE	21	22	(9) UNKNOWN RECLINER MECHANISM HELD (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	36	37
(9) UNKNOWN FRONT SEAT DAMAGE (0) NONE (1) BACKREST ONLY DAMAGED (2) CUSHION ONLY DAMAGED (3) BACKREST & CUSHION DAMAGED (8) NOT APPLICABLE (9) UNKNOWN	25	⊘ 26	HEAD RESTRAINT HEAD RESTRAINT TYPE (0) NONE (1) ADJUSTABLE (2) INTEGRAL (3) NOT INTEGRAL, BUT CANNOT BE REMOVED (7) OTHER: (8) NOT APPLICABLE	2 38	<u>2</u>
CENTER ARMREST DAMAGED (0) NO (1) YES (7) EQUIPPED, DAMAGE UNKNOWN (8) NOT APPLICABLE (NO CENTER ARMREST) (9) UNKNOWN IF EQUIPPED	<u></u>	7	(9) UNKNOWN REMOVED PRE-CRASH (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	8	8 4
FRONT SEAT ROTATION (0) NONE APPARENT (1) FORWARD APPARENT (2) REARWARD APPARENT (3) LEFT APPARENT (4) RIGHT APPARENT (5) MULTIPLE ROTATIONS SPECIFY (8) NOT APPLICABLE (9) UNKNOWN	28	<u>Ø</u>	ADJUSTMENT AT CRASH (1) UP (2) DOWN (8) NOT APPLICABLE (9) UNKNOWN HEAD RESTRAINT DAMAGE (0) NONE (1) DAMAGED BUT NOT SEPARATED (2) SEPARATED (8) NOT APPLICABLE (9) UNKNOWN	<u>8</u>	43


	<u>.</u>		SE	ATS S	ST-2
FRONT SEAT ADJUSTMENT SEAT ADJUSTMENT TYPE (0) NONE (RIGID) (1) MANUAL (2) POWER (7) OTHER: (8) NOT APPLICABLE (NO SEAT) (9) UNKNOWN ADJUSTMENT PROVIDED (1) 2-WAY	DRIVER	PASSEN'R	SECOND SEAT (CONT.) CENTER ARMREST DAMAGED (0) NO (1) YES (7) EQUIPPED, DAMAGE UNKNOWN (8) NOT APPLICABLE (NO CENTER ARMREST) (9) UNKNOWN IF EQUIPPED	\frac{\frac{1}{2}}{6}	0
(2) 4-WAY (3) 6-WAY (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN SEAT ADJUSTER DAMAGE (0) NONE (1) CHUCKING (FREE PLAY) (2) DEFORMED (RELEASED/JAMMED) (3) SEPARATED (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN	48	49	SECOND SEAT-BACK LOCKS FOR THE FOLLOWING, USE: (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN LEFT OR CENTER, EQUIPPED	LEFT	Right 8
SEAT ADJUSTER SEPARATION (0) NONE (1) SEPARATED AT FLOOR (2) SEPARATION OF ADJUSTER (3) SEPARATED AT SEAT (8) NOT APPLICABLE (9) UNKNOWN PRE-CRASH POSITION (1) FORWARD (2) MIDDLE (3) REARWARD (8) NOT APPLICABLE	<u>S</u> 52	8 53 55	LEFT OR CENTER, HELD (3) SEAT FOLDED DOWN RIGHT, EQUIPPED RIGHT, HELD (3) SEAT FOLDED DOWN THIRD SEAT	00 5 00	% % % % % % % %
SECOND SEAT TYPE OF SECOND SEAT (0) NONE (1) NON-FOLDING (2) FOLDING (3) CAPTAIN'S CHAIR (4) JUMP SEAT	LEFT 2 556	Я _І GHT	EQUIPPED BACKREST DAMAGED CUSHION DAMAGED	80 77 80 73 73 73	Ø 70 8 72 8 74
(5) INTEGRAL CHILD SEAT (6) LUGGAGE AREA ACCESS PANEL (9) UNKNOWN SECOND SEAT DAMAGE (0) NONE (1) BACKREST ONLY (DAMAGED OR LOOSENED) (2) CUSHION ONLY (DAMAGED OR LOOSENED) (3) BACKREST & CUSHION (DAMAGED OR LOOSENED) (4) INTEGRAL CHILD SEAT (PRIORITY CODE) (5) LUGGAGE AREA ACCESS PANEL (DAMAGED OR LOOSENED) (8) NOT APPLICABLE (9) UNKNOWN	58	59	VEHICLE EQUIPPED WITH REAR HEAD RESTRAINTS (0) NOT EQUIPPED (OR REMOVED) (1) EQUIPPED (2) EQUIPPED & DAMAGED (8) NOT APPLICABLE (NO REAR SEAT) (9) UNKNOWN Applies to any rear-seat position		⊅ 75

Duplicate columns 1-8 from the previous card. Module A B Format C 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 12	AIRBAG	AB-1
DRIVER SIDE LOCATION OF AIRBAG STEERING WHEEL EQUIPPED (0) NO (1) YES (4) PRIOR DEPLOYMENT NOT REINSTALLED (9) UNKNOWN IF AIRBAG EQUIPPED DEPLOYED (0) NO (1) YES (2) PARTIAL/IMPROPER DEPLOYMENT (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN	13	PASSENGER SIDE LOCATION OF AIRBAG INSTRUMENT PANEL (GLOVE BOX) EQUIPPED (0) NO (1) YES (4) PRIOR DEPLOYMENT NOT REINSTALLED (9) UNKNOWN IF AIRBAG EQUIPPED DEPLOYED (0) NO (1) YES (2) PARTIAL/IMPROPER DEPLOYMENT (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN	16
CONDITION OF AIRBAG STEERING WHEEL (0) NO DAMAGE (2) SPLIT OR TORN (3) CUT DURING CRASH (4) BURNED/MELTED (5) CUT POST CRASH (6) OTHER (7) DAMAGED, CONDITION UNKNOWN (8) NOT APPLICABLE (NOT EQUIPPEDNOT DEPLOYED) (9) UNKNOWN IF EQUIPPED OR CONDITION	15	CONDITION OF AIRBAG INSTRUMENT PANEL (GLOVE BOX) (0) NO DAMAGE (2) SPLIT OR TORN (3) CUT DURING CRASH (4) BURNED/MELTED (5) CUT POST CRASH (6) OTHER (7) DAMAGED, CONDITION UNKNOWN (8) NOT APPLICABLE (NOT EQUIPPED OR CONDITION OR CONDITION	Q
DRIVER SIDE AIRBAG STEERING WHEEL TETHER (0) NO (1) YES (6) OTHER (7) UNKNOWN IF TETHERED (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN IF AIRBAG EQUIPPED	19	PASSENGER SIDE AIRBAG INSTRUMENT PANEL (GLOVE BOX) TETHER (0) NO (1) YES (6) OTHER (7) UNKNOWN IF TETHERED (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN IF AIRBAG EQUIPPED	<u></u>
MARKED BY CONTACT (0) NO (1) YES (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN	Q	MARKED BY CONTACT (0) NO (1) YES (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN	Q_{z}

AIRBAG NUMBER ON DRIVER SIDE:




NOTE AND DESCRIBE ANY AIRBAG CONTACT OR DAMAGE ON DIAGRAM BELOW:




Bas cut out of Steering - wheel

AIRBAG NUMBER ON PASSENGER SIDE:



NOTE AND DESCRIBE ANY AIRBAG CONTACT OR DAMAGE ON DIAGRAM BELOW:



Blood on top, front and sides of by

NOTE TO THE INVESTIGATOR:

THE FOLLOWING TWO SECTIONS,

OCCUPANT INFORMATION AND INJURY CLASSIFICATION,

ARE TO BE FILLED IN

FOR EACH CASE VEHICLE OCCUPANT,

WHETHER INJURED OR NOT.

IF THERE IS MORE THAN ONE OCCUPANT,
USE ADDITIONAL COPIES
OF PAGES OC-1, OC-2, OC-3,
AND IC-2 TO DESCRIBE THEM
AND ATTACH THE COPIES TO THIS REPORT.

Duplicate columns 1-8 from the previous card. Module O C Format C) <u>2</u> 1 12	Occupant Information ()C-1
OCCUPANT IDENTIFICATION OCCUPANT NUMBER ROLE OF OCCUPANT AT 1ST IMPACT (1) MOTOR VEHICLE DRIVER (2) MOTOR VEHICLE PASSENGER (NOT DRIVER) (9) UNKNOWN	13 14 15	PHYSICAL DESCRIPTION AGE IN YEARS (00) LESS THAN 1 YEAR (98) 98 YEARS OR OLDER (99) UNKNOWN AGE IN MONTHS (00) LESS THAN 1 MONTH (25) 25 MONTHS OR OLDER (99) UNKNOWN	$\frac{63}{20}$
OCCUPANT POSITION ROW LOCATION (1) FRONT (2) SECOND (3) THIRD (4) FOURTH (7) OTHER: (8) EXTERNAL TO PASSENGER COMPARTMENT (E.G. BED OF PICKUP) (9) UNKNOWN	16	MASS (kg) (999) UNKNOWN HEIGHT (cm) (999) UNKNOWN SEX (1) MALE (2) FEMALE (9) UNKNOWN	$ \frac{09}{24} = \frac{162}{25} $ $ \frac{162}{27} = \frac{28}{28} $
LATERAL LOCATION (1) LEFT (2) LEFT CENTER (3) CENTER (4) RIGHT CENTER (5) RIGHT (6) ALL (LYING ON SEAT) (8) EXTERNAL TO PASSENGER COMPARTMENT (9) UNKNOWN POSTURE (10) SITTING ON SEAT	10	MEDICAL CONDITIONS TREATMENT/MORTALITY (00) NONE (01) FIRST AID AT SCENE (02) TREATED AT HOSPITAL/CLINIC BUT NOT ADMITTED (03) HOSPITALIZED FOR OBSERVATION LESS THAN 24 HOURS (04) HOSPITALIZED OVER 24 HOURS OR FOR SIGNIFICANT TREATMENT (05) FATAL, DEAD AT SCENE (06) FATAL, DOA (07) FATAL, DEAD WITHIN 24 HOURS (08) FATAL, DEAD 24 HOURS TO 31 DAYS LATER (09) FATAL, DEAD 31 DAYS TO	$\frac{99}{31}$
(10) SITTING ON SEAT IN ABNORMAL POSITION (E.G. FEET ON DASH, SIDEWAYS) (12) SITTING ON CONSOLE (20) ON LAP OR IN ARMS (30) STANDING ON SEAT (40) STANDING ON FLOOR (47) STANDING, EXTERNAL TO PASSENGER COMPARTMENT (50) IN BASSINET (60) IN CHILD SEAT (65) IN CHILD HARNESS (70) LYING ON SEAT (80) LYING/SITTING ON PASSENGER FLOOR (83) LYING/SITTING ON OTHER OBJECT IN PASSENGER COMPARTMENT: (85) ON CARGO FLOOR/FOLDED SEAT-BACK	18 19	(09) FATAL, DEAD 31 DAYS TO 1 YEAR LATER (10) FATAL DEAD WITHIN UNKNOWN PERIOD (99) UNKNOWN INJURY SEVERITY SCORE (ISS) (99) UNKNOWN NON-IMPACT MED. CONDITIONS (0) NONE (1) YES, TIME & TYPE UNKNOWN (2) PRE-CRASH FATAL (CLINICAL DEATH AT WHEEL) (3) PRE-CRASH NON-FATAL (E.G. PRIOR INJURY, STROKE) (4) PREGNANT (5) POST-CRASH FATAL (DROWNING) (6) POST-CRASH NON-FATAL INJURY	nknou
(87) LYING/SITTING, EXTERNAL TO PASSENGER COMPARTMENT (97) OTHER: (99) UNKNOWN		(7) OTHER: (8) COMBINATION OF ABOVE (CIRCLE EACH) (9) UNKNOWN	

		OCCUPANT INFORMATION C)C-2
MEDICAL CONDITIONS (CONT.) POLICE INJURY SEVERITY CODE FOR THIS OCCUPANT (0) O - NO INJURY (1) C - POSSIBLE INJURY (2) B - NON-INCAPACITATING (3) A - INCAPACITATING INJURY (4) K - FATAL (5) INJURED, SEVERITY UNKNOWN (6) DIED PRIOR TO IMPACT (7) NON-FATAL INJURY, SEVERITY UNKNOWN (9) UNKNOWN	3/36	CHILD SEAT TYPE (00) NONE USED (01) YES, USED (02) INTEGRAL, Chrysler Mini-van (88) NOT APPLICABLE (ADULT OR OLDER CHILD) (99) UNKNOWN CHILD SEAT MAKE/MODEL	8 9 41
ACTIVE RESTRAINT SYSTEM (0) NONE (1) LAP BELT (2) SHOULDER HARNESS ONLY (3) BOTH LAP BELT & SHOULDER HARNESS (9) UNKNOWN ACTIVE RESTRAINT SYSTEM USAGE (0) NONE (AVAILABLE BUT NOT USED) (1) LAP BELT ONLY (2) SHOULDER HARNESS ONLY (3) BOTH LAP BELT & SHOULDER HARNESS (7) IMPROPER USAGE (8) NOT APPLICABLE (NONE AVAILABLE) (9) UNKNOWN PASSIVE RESTRAINT SYSTEM (0) NONE (1) AIRBAG INSTALLED (2) PASSIVE UPPER TORSO WITH KNEE BOLSTERS (3) PASSIVE UPPER TORSO WITHOUT KNEE BOLSTERS (4) PASSIVE LAP & UPPER TORSO (5) AIRBAG INSTALLED & PASSIVE RESTRAINT (7) OTHER: (9) UNKNOWN PASSIVE RESTRAINT SYSTEM USAGE (0) SYSTEM DEFEATED (1) AIRBAG NOT DEPLOYED	$\frac{3}{37}$ $\frac{1}{39}$	EJECTION (0) NONE (1) PARTIAL (2) COMPLETE (7) EJECTED, DEGREE UNKNOWN (9) UNKNOWN IF EJECTED AREA OF EJECTION (01) WINDOW, LEFT SIDE (02) WINDOW, RIGHT SIDE (03) WINDOW, REAR (04) DOOR, LEFT SIDE (05) DOOR, RIGHT SIDE (06) DOOR, RIGHT SIDE (07) WINDSHIELD (08) ROOF OR OPEN CONVERTIBLE OR FROM EXTERNAL AREA (96) EJECTED AREA UNKNOWN (97) OTHER AREA: (98) NOT APPLICABLE (NOT EJECTED) (99) UNKNOWN IF EJECTED	P 43 44 45
(1) AIRBAG NOT DEPLOYED (2) AIRBAG DEPLOYED (3) AIRBAG NOT REINSTALLED (4) PASSIVE UPPER TORSO USED (5) PASSIVE LAP & UPPER TORSO USED (6) SYSTEM USED IN MANUAL MODE (7) IMPROPER USAGE (8) NOT APPLICABLE (NOT ORIGINALLY EQUIPPED) (9) UNKNOWN	40	HEAD RESTRAINT HEAD RESTRAINT AVAILABLE FOR THIS POSITION (0) NOT EQUIPPED OR REMOVED (1) EQUIPPED (9) UNKNOWN	1 46

		OCCUPANT INFORMATION (OC-3
OCCUPANT EYEWEAR (0) NONE (1) GLASSES (2) CONTACTS (3) BOTH GLASSES AND CONTACTS (4) OTHER (8) NOT APPLICABLE (9) UNKNOWN	9 47	SOURCE OF INFORMATION (0) INTERVIEW (1) HOSPITAL (2) AUTOPSY (3) POLICE (4) OTHER (5) LAY CORONER/EXTERNAL EXAM (7) COMBINATION OF ABOVE (CIRCLE) (8) NOT APPLICABLE (9) UNKNOWN Several attempts	3 48


were made to contact this occupant, but the phone was never answered.


No answering machine

OCCUPANT INFORMATION OC-4

INDICATE LOCATION OF INJURIES.

Police reported "A" injuries





INJURY CLASSIFICATION IC-1

Duplicate columns 1-8 from the previous card.

NOTE: Each line in the table below is a separate record (card).

Duplicate columns 1 - 12 for each completed line.

OCCUPANT INJURY CLASSIFICATION

						PRIM	ARY C	DIC		Α:	ssoc	ATE	OIC		СОММ	ENTS
OCCUPANT NUMBER	INJURY NUMBER	PROBAE START V IN 1ST C	BILITY (HORI WITH MOST I CONTACT AR	N ORDER OF ZONTALLY) . PROBABLE IEA COLUMN. LE CONTACT	BODY REGION 1	ASPECT Q	LESION 3	SYSTEM/ORGAN 4	SEVERITY LO	BODY REGION 1	ASPECT Q	LESION 3	SYSTEM/ORGAN 4	SEVERITY 15		
13-14	15-16	17-18	19-20	COMMENTS	21	22	23	24	25	26	27	28	29	30		
01	01	99			¥	¥	U	U	9	-	_		_	-		
Î					-	_		_	_	_		_	_	_		
					-	_	_	_		_	_	_	-	-		
					-		_	_	-		_		_	-		
					<u> </u>	_	_	_	-	_	_	_		-		
					-	_	_	_	. —	_	_	_	_	-		
					-					_	_	_		-		
<u>ë</u>					-		_			_		_		-		
te "Occupant Number" for each line.					-				-		_		_	-		
'umber"					-		_	_	-	_	_	_		-		
ccupant P					-	_	_	_	-		_			-		
icate O					-	_	_	-	-	-	_	_		_		
Duplica					-	_	_	_	-	-	-	_	_	-		
					-	_	_		-	-	_	_	-	-		
					-		_		-	_	_	_	_	-		
					-	_	_	_	*	_	_	_		-		
					-				-	_	_		_	-		
]			— a			<u> </u>	_	_	_	_	_	_		

INJURY CLASSIFICATION IC-2

CODES FOR AREAS OF POSSIBLE OCCUPANT CONTACT

		D O		
		OF PASSENGER COMPARTMENT	SIDES	
	(10)	. , , , , , , , , , , , , , , , , , , ,	(20)	SURFACE OF SIDE INTERIOR
(12)	WINDSHIELD	(19)	
			(13)	
((05)	INSTRUMENT PANEL (SPECIFIC AREA UNKNOWN)	(24)	
(54)	UPPER INSTRUMENT PANEL (X)	(,	JOHN HOOK
i	55)	MIDDLE INSTRUMENT PANEL (Y)	(22)	WINDOW CLASS (CIDE)
,	56)	LOWER INSTRUMENT PANEL (Z)		
	81)	ASH TRAY (INSTRUMENT PANEL)	(21)	WINDOW FRAMES (SIDE)
	02)	GLOVE COMPARTMENT AREA		
		AIRBAG (ACRS) COMPARTMENT DOOR/COVER	(26)	ROOF SIDE RAIL
4.	47)	AIRBAG (ACAS) COMPARTMENT DOON/COVER	(14)	A-PILLAR
		DENEATH MOTOR MENT DAVIS	(15)	B-PILLAR
•	57)	BENEATH INSTRUMENT PANEL	(16)	C-PILLAR
	53)	PARCEL TRAY	(17)	D-PILLAR
	48)	KNEE RESTRAINT		
(8	B6)	VERTICAL CONSOLE	FLOOR	
				FLOOR
(2	28)	FOOT CONTROLS (INCL. PARKING BRAKE PEDAL)	(27)	
		•		TRANSMISSION LEVER ON FLOOR OR CONSOLE
(0	09)	STEERING ASSEMBLY (SPECIFIC AREA UNKNOWN)	(85)	
(6	35)	STEERING WHEEL	(28)	THE PROPERTY OF THE PROPERTY O
•	3 6)	STEERING WHEEL COLUMN	• •	FOOT CONTROLS (INCL. PARKING BRAKE PEDAL) KICKPANEL
•	59)	TRANSMISSION LEVER ON COLUMN	(91)	KICKPANEL
,-	,	THE RESIDENCE OF THE PROPERTY	Poor	
"	03)	HADDWADE ITEM (SDECIEIC AREA LINKNOWN)	Roof	
	•	HARDWARE ITEM (SPECIFIC AREA UNKNOWN) INSTRUMENT(S)	(25)	
	32)		(10)	SUNVISOR, FITTING(S) &/OR TOP MOLDING
•	33)	CONTROL KNOB(S) & LEVER(S) (FRONT)	(26)	ROOF SIDE RAIL
•	34)	PARKING BRAKE HANDLE IN FRONT	(24)	COAT HOOK
	i7)	IGNITION KEY	(18)	DOME LIGHT
(0)6)	MIRROR	(39)	BACKLIGHT HEADER
(0	14)	HEATER OR AIR CONDITIONING DUCTS	(68)	
(0	11)	AIR CONDITIONING OR VENTILATION OUTLET(S)	(69)	ROLL BAR
(0	8)	RADIO (BUILT IN)		*
(5	8)	ADD-ON TAPE DECK, RADIO, A/C	EXTERIO	OR SURFACE OF CASE VEHICLE
(6	8)	ROOF MOUNTED CONTROLS/CONSOLES	(37)	OUTSIDE SURFACE OF CASE VEHICLE
•-	-,		(31)	
REAR			(05)	(SPECIFIC AREA UNKNOWN)
		SURFACE OF REAR INTERIOR	(35)	HOOD OF CASE VEHICLE
•	•	REAR WINDOW	(60)	EXTERIOR OF CASE VEHICLE (E.G.
•	•			OUTSIDE MIRRORS, ANTENNA, TRIM)
•	•	REAR WINDOW HEADER	(62)	EXTERIOR SIDE ROOF RAIL OF CASE VEHICLE
(5	U)	REAR SEAT CUSHION & BACK	(63)	TRUNK LID OF CASE VEHICLE
		0	(64)	TIRES OF CASE VEHICLE
		-GENERAL		
(1		TRANSMISSION SELECTION LEVER (LOCATION UNK.)	BEYOND	CASE VEHICLE BOUNDARY
(59	9)	TRANSMISSION LEVER ON STEERING COLUMN	(36)	AREA EXTERIOR TO CAR (SPECIFIC AREA UNK.)
(44		TRANSMISSION LEVER ON FLOOR OR CONSOLE	(70)	HOOD OF OTHER VEHICLE
(0)	7)	PARKING BRAKE HANDLE (LOCATION UNKNOWN)	(71)	OTHER VEHICLE EXTERIOR HARDWARE (E.G.
(84		PARKING BRAKE HANDLE IN FRONT	(, ,	OUTSIDE MIRRORS, ANTENNA, TRIM)
(85	5)	PARKING BRAKE HANDLE ON FLOOR OR CONSOLE	(73)	EXTERIOR CIDE DOOR DAIL OF COLUMN
(28	B)	FOOT CONTROLS (INCL. PARKING BRAKE PEDAL)	(74)	EXTERIOR SIDE ROOF RAIL OF OTHER VEHICLE
	•	(I all the state of the state	<u>`</u> :	HEADLIGHT OR FRONT GRILL OF OTHER VEH.
(29	9)	FRONT SEAT-BACK(S)	(75)	TRUNK OF OTHER VEHICLE
(51	•	FRONT SEAT CUSHION	(76)	OUTSIDE SURFACE OF OTHER VEHICLE
(50	•	REAR SEAT CUSHION & BACK	(77)	TIRES OF OTHER VEHICLE
•	•		(78)	GROUND
(49		ARMREST ON SEAT	(79)	WATER
(89	9)	UNDER SEAT BOTTOM	(80)	EXTERIOR OBJECT (NOT VEHICLE, GROUND,
				OR WATER. PLEASE DESCRIBE.)
(33	•	RESTRAINT SYSTEM HARDWARE		
(34	1)	RESTRAINT SYSTEM WEBBING	PENETRA	ATING OBJECTS
(87	7)	AIR CUSHION SKIN (AIRBAG)		OTHER VEHICLE
(47	7)	AIRBAG (ACRS) COMPARTMENT DOOR/COVER	(72)	OBJECTS (DESCRIBE)
(46	-	AIRBAG GAS	\· - /	TITLE TO (DECOTIOE)
(48	•	KNEE RESTRAINT	MISCELL	ANEOUS
(30	•	HEAD RESTRAINT		
(42		CHILD SEAT RESTRAINTS	(00)	NO CONTACT (INVALID FIELD FORM CODE)
(43	•	CHILD SEAT		OTHER (E.G. FIRE. DESCRIBE)
(31	•	INTERIOR LOOSE OBJECT	(90)	- · · · · -
(32	•	OTHER OCCUPANT(S)	(96)	INDUCED
(52)		INTERNAL FLYING GLASS (FROM ANY SOURCE)	(97)	
(41)			(98)	IMPACT FORCE, "WHIPLASH",
(+ 1)	, '	UNKNOWN INTERIOR SURFACE		HYPEREXTENSION/COMPRESSION

(99) UNKNOWN AREA OF CONTACT

CODES FOR OCCUPANT INJURY CLASSIFICATION (OIC)

1 BODY REGION

- (H) HEAD/SKULL
- (F) FACE
- (N) NECK
- (S) SHOULDER
- (X) UPPER EXTREMITIES
- (A) ARM (UPPER)
- (E) ELBOW
- (R) FOREARM
- (W) WRIST/HAND
- (C) CHEST
- (M) ABDOMEN
- (B) BACK
- (P) PELVIC/HIP
- (Y) LOWER EXTREMITIES
- (T) THIGH
- (K) KNEE
- (L) LEG (LOWER)
- (Q) ANKLE/FOOT
- (O) WHOLE BODY
- (U) UNKNOWN

3 LESION

- (L) LACERATION
- (C) CONTUSION
- (A) ABRASION
- (F) FRACTURE
- (P) PERFORATION, PUNCTURE
- (K) CONCUSSION
- (V) AVULSION
- (R) RUPTURE
- (S) SPRAIN
- (D) DISLOCATION
- (N) CRUSH
- (M) AMPUTATION
- (B) BURN
- (G) DETACHMENT, SEPARATION
- (Z) FRACTURE AND DISLOCATION
- (T) STRAIN
- (E) TOTAL SEVERANCE, TRANSECTION
- (O) OTHER
- (U) UNKNOWN

4 SYSTEM/ORGAN

- (S) SKELETAL
- (V) VERTEBRAE
- (J) JOINTS
- (D) DIGESTIVE
- (L) LIVER
- (N) NERVOUS SYSTEM
- (B) BRAIN
- (C) SPINAL CORD
- (E) EARS
- (O) EYES
- (A) ARTERIES
- (H) HEART
- (Q) SPLEEN
- (G) UROGENITAL
- (K) KIDNEYS
- (R) RESPIRATORY
- (P) PULMONARY/LUNGS
- (M) MUSCLES
- (T) THYROID, OTHER ENDOCRINE GLAND
- (I) INTEGUMENTARY (SKIN)
- (W) ALL SYSTEMS IN REGION
- (U) UNKNOWN

2 ASPECT

- (R) RIGHT
- (L) LEFT
- (B) BILATERAL
- (C) CENTRAL
- (A) ANTERIOR/FRONT
- (P) POSTERIOR/BACK
- (S) SUPERIOR/UPPER
- (I) INFERIOR/LOWER
- (W) WHOLE REGION
- (U) UNKNOWN

SEVERITY 5
SYSTEM/ORGAN 4
LESION 9
ASPECT 0
BODY REGION 1

SEVERITY (OR "AIS", ABBREVIATED INJURY SCALE)


- (0) NONE
- (1) MINOR
- (2) MODERATE
- (3) SERIOUS
- (4) SEVERE
- (5) CRITICAL
- (6) MAXIMUM
- (9) UNKNOWN

PHYSICAL DESCRIPTION AGE IN YEARS (00) LESS THAN 1 YEAR (98) 98 YEARS OR OLDER (99) UNKNOWN AGE IN MONTHS (00) LESS THAN 1 MONTH (25) 25 MONTHS OR OLDER (99) UNKNOWN MASS (kg) (999) UNKNOWN HEIGHT (cm) (999) UNKNOWN	7 4 2 5 2 23 2 24 25
(999) UNKNOWN HEIGHT (cm)	
SEX (1) MALE (2) FEMALE (9) UNKNOWN	183 27 28 M 30
MEDICAL CONDITIONS TREATMENT/MORTALITY (00) NONE (01) FIRST AID AT SCENE (02) TREATED AT HOSPITAL/CLINIC BUT NOT ADMITTED (03) HOSPITALIZED FOR OBSERVATION LESS THAN 24 HOURS (04) HOSPITALIZED OVER 24 HOURS OR FOR SIGNIFICANT TREATMENT (05) FATAL, DEAD AT SCENE (06) FATAL, DOA	<u>Q</u> 4
(07) FATAL, DEAD WITHIN 24 HOURS (08) FATAL, DEAD 24 HOURS TO 31 DAYS LATER (09) FATAL, DEAD 31 DAYS TO 1 YEAR LATER (10) FATAL DEAD WITHIN UNKNOWN PERIOD (99) UNKNOWN INJURY SEVERITY SCORE (ISS) (99) UNKNOWN NON-IMPACT MED. CONDITIONS (0) NONE (1) YES, TIME & TYPE UNKNOWN (2) PRE-CRASH FATAL (CLINICAL DEATH AT WHEEL) (3) PRE-CRASH FATAL (E.G. PRIOR INJURY, STROKE) (4) PREGNANT (5) POST-CRASH FATAL (DROWNING) (6) POST-CRASH NON-FATAL INJURY (7) OTHER: QN QUY YSMS OF IMAC	7 35
	(08) FATAL, DEAD 24 HOURS TO 31 DAYS LATER (09) FATAL, DEAD 31 DAYS TO 1 YEAR LATER (10) FATAL DEAD WITHIN UNKNOWN PERIOD (99) UNKNOWN INJURY SEVERITY SCORE (ISS) (99) UNKNOWN NON-IMPACT MED. CONDITIONS (0) NONE (1) YES, TIME & TYPE UNKNOWN (2) PRE-CRASH FATAL (CLINICAL DEATH AT WHEEL) (3) PRE-CRASH NON-FATAL (E.G. PRIOR INJURY, STROKE) (4) PREGNANT (5) POST-CRASH NON-FATAL INJURY

		OCCUPANT INFORMATION (OC-2
MEDICAL CONDITIONS (CONT.) POLICE INJURY SEVERITY CODE FOR THIS OCCUPANT (0) O - NO INJURY (1) C - POSSIBLE INJURY (2) B - NON-INCAPACITATING (3) A - INCAPACITATING INJURY (4) K - FATAL (5) INJURED, SEVERITY UNKNOWN (6) DIED PRIOR TO IMPACT (7) NON-FATAL INJURY, SEVERITY UNKNOWN (9) UNKNOWN	3	CHILD SEAT TYPE (00) NONE USED (01) YES, USED (02) INTEGRAL, Chrysler Mini-van (88) NOT APPLICABLE (ADULT OR OLDER CHILD) (99) UNKNOWN CHILD SEAT MAKE/MODEL	8 8
RESTRAINT SYSTEM (0) NONE (1) LAP BELT (2) SHOULDER HARNESS ONLY (3) BOTH LAP BELT & SHOULDER HARNESS (9) UNKNOWN ACTIVE RESTRAINT SYSTEM USAGE (0) NONE (AVAILABLE BUT NOT USED) (1) LAP BELT ONLY (2) SHOULDER HARNESS ONLY (3) BOTH LAP BELT & SHOULDER HARNESS (7) IMPROPER USAGE (8) NOT APPLICABLE (NONE AVAILABLE) (9) UNKNOWN PASSIVE RESTRAINT SYSTEM (0) NONE (1) AIR BAG INSTALLED (2) PASSIVE UPPER TORSO WITH KNEE BOLSTERS (3) PASSIVE UPPER TORSO WITHOUT KNEE BOLSTERS (4) PASSIVE LAP & UPPER TORSO (5) AIR BAG INSTALLED & PASSIVE RESTRAINT (7) OTHER: (9) UNKNOWN	3 37	EJECTION DEGREE OF EJECTION (0) NONE (1) PARTIAL (2) COMPLETE (7) EJECTED, DEGREE UNKNOWN (9) UNKNOWN IF EJECTED AREA OF EJECTION (01) WINDOW, LEFT SIDE (02) WINDOW, RIGHT SIDE (03) WINDOW, REAR (04) DOOR, LEFT SIDE (05) DOOR, RIGHT SIDE (06) DOOR, REAR OR TAILGATE (07) WINDSHIELD (08) ROOF OR OPEN CONVERTIBLE OR FROM EXTERNAL AREA (96) EJECTED AREA UNKNOWN (97) OTHER AREA: (98) NOT APPLICABLE (NOT EJECTED) (99) UNKNOWN IF EJECTED	98 45
PASSIVE RESTRAINT SYSTEM USAGE (0) SYSTEM DEFEATED (1) AIR BAG NOT DEPLOYED (2) AIR BAG DEPLOYED (3) AIR BAG NOT REINSTALLED (4) PASSIVE UPPER TORSO USED (5) PASSIVE LAP & UPPER TORSO USED (6) SYSTEM USED IN MANUAL MODE (7) IMPROPER USAGE (8) NOT APPLICABLE (NOT ORIGINALLY EQUIPPED) (9) UNKNOWN	2 -	HEAD RESTRAINT HEAD RESTRAINT AVAILABLE FOR THIS POSITION (0) NOT EQUIPPED OR REMOVED (1) EQUIPPED (9) UNKNOWN	1 46

OCCUPANT INFORMATION (
OCCUPANT EYEWEAR (0) NONE (1) GLASSES (2) CONTACTS (3) BOTH GLASSES AND CONTACTS (4) OTHER (8) NOT APPLICABLE (9) UNKNOWN	7	SOURCE OF INFORMATION (0) INTERVIEW (1) HOSPITAL (2) AUTOSPY (3) POLICE (4) OTHER (7) COMBINATION OF ABOVE (CIRCLE) (8) NOT APPLICABLE (9) UNKNOWN	48						

INDICATE LOCATION OF INJURIES.



INJURY CLASSIFICATION IC-1

Duplicate columns 1-8 from the previous card.

Module | C Format 0 1 12

NOTE: Each line in the table below is a separate record (card).

Duplicate columns 1 - 12 for each completed line.

OCCUPANT INJURY CLASSIFICATION

				SIFICATION	<u>[</u> .	PRIM	ARY C	OIC		A	SSOC	IATED	OIC		COMMENTS
OCCUPANT NUMBER	INJURY NUMBER	PROBAB START V IN 1ST C	BILITY (HOR WITH MOST CONTACT A	IN ORDER OF IZONTALLY) . PROBABLE REA COLUMN. BLE CONTACT	BODY REGION 1	ASPECT Q	LESION 3	SYSTEMORGAN 4	SEVERITY 10	BODY REGION 1	ASPECT O	LESION 3	SYSTEMORGAN 4	SEVERITY LO	
13-14	15-16	17-18	19-20	COMMENTS	21	22	23	24	25	26	27	28	29	30	
Q L	<u>@1</u>	12			E	۲	<u>_</u>	Ī	1	_	_	_	_	_	
1	<u> </u>	12			E	R	<u>C</u>	I	1	_	_	_	_	_	
	03	12			F	<u>R</u>	E	<u>S</u>	<u>3</u>	_			_	4	
	<u>Q4</u>	38			R	<u>R</u>	E	<u>S</u>	<u>3</u>	_		_	_		
	<u>05</u>	48			L	R	F	<u>S</u>	<u>3</u>	_	_	_	_	_	
	06	48			<u>k</u>	<u>L</u>	F	<u>S</u>	<u> </u>	_	_		_		
•	<u>07</u>	12			F	<u>c</u>	F	5	2	_	_	_		_	
٠					-	_				-	_		_	_	
"Occupant Number" for each line					_	_	_	_		_	_	_	_	-	
mber fo					 -;	*		_	_	_	_	_	_	_	
upent Nu					_	_	_	. —	· 	-				_	
2					-	_		_	_	_				_	
- Duplica					_	_	-	_	-	_	<u> </u>	. — `	_	-	
					-	_	· —	_	_	-	_	_		_	
						_	_	_		-	_		_	_	
					-	_	_	_	_	_	_				
					-	_	- .	_	_	-	_	<u>-</u>	_	_	
1.					_		_	_		_		_			







st Availal



et Aveilebl



of Available



N 18100#6







et Availabl





















N 18100#19









































































PN 18100#55











PN 18100 #60